

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21009339/GVF3E2

Date: 19/11/2021

REFERENCE

Insured/Claimant: HENG CHOON MENG Policy No: MPC21D00001800
Date of Loss: 02/09/2021 Nature of Claim: OD Claim No: DMPC2100301H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCY59P**
Make & Model: HONDA CIVIC, 2.0 3DRS TYPE R (A) Engine No: K20A5801410
Reg. Date: 22/05/2007 (Man. Year: 2007) Chassis No: FD21201412
Colour: White Odometer: 0 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/45Z R17 Rear Tyre Size: 235/45Z R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,455.18	22,281.16	11,174.02	33.40
Miscellaneous Items	1,205.00	184.15	1,020.85	84.72
Labour	4,810.00	3,820.00	990.00	20.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,470.18	26,285.31	13,184.87	33.40
Approved Total (Overridden) (S\$)		19,000.00		
(S\$)	39,470.18	19,000.00	20,470.18	51.86
+ GST 7.00/7.00% (S\$)	2,762.91	1,330.00	1,432.91	51.86
Nett Amount (S\$)	42,233.09	20,330.00	21,903.09	51.86

INSPECTION

Date of Assignment: 06/09/2021 Present Location: Automobile Integrated Management Pte Ltd (HQ)
Automobile Integrated Management Pte Ltd (HQ)
Date Inspected: 07/09/2021 Inspected At: 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
Singapore 415933
Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2021)
Parts: 143	HONDA CIVIC 2.0 3DRS TYPE R (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCY59P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 THROTTLE BODY (WCP)	Serviceable	1,451.00 F	*- F
2	1		*4 SPARK PLUG COIL X 4 (WCP)	Contaminated	591.60 F	*591.60 F
3	1		*4 SPARK PLUG X 4 @ \$48.30 (WCP)	Contaminated	193.20 F	*193.20 F
4	1		*1 ALTERNATOR ASSY (WCP)	Damaged	1,992.50 F	*900.00 F
5	1		*1 STARTER ASSY (WCP)	Damaged	1,172.90 F	*900.00 F
6	1		*1 ROCKER COVER GASKET (WCP)	Contaminated	253.10 F	*253.10 F
7	1		*1 ENGINE HEAD ASSY (WCP)	Contaminated	4,083.90 F	*3,500.00 F
8	1		*1 ENGINE HEAD GASKET (WCP)	Contaminated	130.00 F	*130.00 F
9	1		*1 ENGINE INTAKE CAMSHAFT SPROCKET (WCP)	Not Necessary	225.30 F	*- F
10	1		*1 ENGINE EXHAUST CAMSHAFT (WCP)	Not Necessary	833.80 F	*- F
11	1		*1 ENGINE EXHAUST CAMSHAFT SPROKET (WCP)	Not Necessary	136.80 F	*- F
12	1		*8 INTAKE VALVE @ \$37.30 (WCP)	Contaminated	298.40 F	*298.40 F
13	1		*8 EXHAUST VALVE @ \$58 (WCP)	Contaminated	464.00 F	*464.00 F
14	1		*8 ROCKER ARM @ \$461.40 (WCP)	Damaged	3,691.20 F	*3,691.20 F
15	1		*1 ENGINE OIL FILTER (WCP)	Contaminated	32.20 F	*32.20 F
16	1		*1 ENGINE OIL COOLER (WCP)	Damaged	820.60 F	*820.60 F
17	1		*1 ENGINE OIL COOLER GASKET (WCP)	Contaminated	4.50 F	*4.50 F
18	1		*1 ENGINE OIL PUMP ASSY (WCP)	Contaminated	434.10 F	*434.10 F
19	1		*1 ENGINE BLOCK ASSY (WCP)	Repair	4,643.40 F	*- F
20	1		*1 ENGINE CRANKSHAFT GASKET (WCP)	Contaminated	24.10 F	*24.10 F
21	1		*1 ENGINE COOLANT PUMP WITH GASKET ASSY (WCP)	Not Necessary	263.40 F	*- F
22	1		*1 ENGINE THERMOSTAT (WCP)	Contaminated	78.00 F	*78.00 F
23	1		*1 ENGINE CRANKSHAFT (WCP)	Broken	1,602.60 F	*1,602.60 F
24	1		*5 ENGINE CRANKSHAFT BEARING UP @ \$20.30 (WCP)	Necessary	101.50 F	*101.50 F
25	1		*5 ENGINE CRANKSHAFT BEARING LOW @ \$28.40 (WCP)	Necessary	142.00 F	*142.00 F
26	1		*2 ENGINE CRANKSHAFT WASHER @ \$11.30 (WCP)	Necessary	22.60 F	*22.60 F
27	1		*4 ENGINE PISTON RING @ \$72.70 (WCP)	Necessary	290.80 F	*290.80 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*4 ENGINE PISTON @ \$120.10 (WCP)	Bent	480.40 F	*480.40 F
29	1		*4 ENGINE PISTON CON ROD @ \$201 (WCP)	Bent	804.00 F	*804.00 F
30	1		*8 ENGINE PISTON CON ROD BEARING @ \$18.50 (WCP)	Bent	148.00 F	*148.00 F
31	1		*1 ENGINE HEAD GASKET SET (WCP)	Contaminated	450.50 F	*450.50 F
32	1		*1 ENGINE BLOCK GASKET SET (WCP)	Contaminated	58.10 F	*58.10 F
33	1		*1 ENGINE INTAKE AIR FILTER (WCP)	Contaminated	86.00 F	*86.00 F
34	1		*1 FUEL CANISTER ASSY (WCP)	Contaminated	201.60 F	*201.60 F
35	1		*1 ENGINE CONTROL UNIT (WCP)	Contaminated	2,455.20 F	*1,800.00 F
36	1		*1 ENGINE REPLAY BOX ASSY (WCP)	Contaminated	283.60 F	*283.60 F
37	1		*2 FRONT DOOR SPEAKERS @ \$150 (WCP)	Contaminated	300.00 F	*300.00 F
38	1		*1 AIRCON FAN MOTOR (WCP)	Contaminated	225.00 F	*225.00 F
39	1		*1 REDIATOR FAN MOTOR (WCP)	Contaminated	250.00 F	*250.00 F
40	1		*1 AIRCON COOLING COIL (WCP)	Contaminated	480.00 F	*480.00 F
41	1		*1 ENGINE TIMING CHSIN COVER WITH GASKET (WCP)	Contaminated	213.90 F	*213.90 F

F=Franchise part.

Sub Total (\$)	30,413.80	20,255.60
+ Margin on L,N Items 10.00/10.00% (\$)	3,041.38	2,025.56
Total Parts (\$)	33,455.18	22,281.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1L POWER STEERING FLUID (NECESSARY) (50%)	19.50	9.75
2	1	4 GASKET GUM (NECESSARY)	58.80	50.00
3	1	4L AUTO TRANSMISSION FLUID (NECESSARY) (50%)	903.40	45.20
4	1	4L BRAKE FLUID (NECESSARY) (50%)	39.90	19.95
5	1	4L ENGINE COOLANT (NOT NECESSARY)	64.60	0.00
6	1	4L ENGINE OIL (NECESSARY) (50%)	118.80	59.25
Sub Total (\$\$)			1,205.00	184.15

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PERFORM FULL ENGINE OVERHAUL	New	2,000.00	2,000.00
2	TO CONDUCT DIANOGIS RESET ON FAULTY CODE	New	800.00	400.00
3	REMOVE & REFIX SEAT CUSHION , UPHOLSTERY , INTERIOR TRIMMING ETC FOR DRY UP	New	800.00	400.00
4	TO REMOVE & REFIX ENGINE GEARBOX ETCS	New	400.00	380.00
5	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	380.00	300.00
6	TO CONDUCT WHEEL ALIGNMENT	New	80.00	60.00
7	TO REMOVE & SERVICE AIRCON BLOWER , REFILL AIRCON GAS	New	250.00	180.00
8	TO REMOVE & SERVICE EXHAUST SYSTEM	New	100.00	100.00
Gross Labour Cost (\$\$)			4,810.00	3,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >