

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Liu Chun Cheong

Date: 02 Nov 2021

Preliminary Advice

Vehicle No	: SCY59P	Accident Date	: 02/09/2021
Make	: HONDA CIVIC	Policy No.	: MPC21D00001800
Assignment Date	: 06/09/2021	Excess	: S\$0.00
Date of Inspection	: 07/09/2021	Est. Duration of Repair	: 12
Inspection At	: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01, KAKI BUKIT (SOUTH WING) SINGAPORE 415933		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,575.24
Revised Amount	:S\$	26,285.31
Check Items (Estimated)	:S\$	0.00
Total	:S\$	26,285.31
Lump Sum Repair	:S\$	20,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	29,942.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,058.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :