

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21009342/VRS3Q2  
**Date:** 03/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900091718-01
<b>Claimant Vehicle No :</b>	SHA5727D	<b>Insured Vehicle No :</b>	SML5983M
Date of Loss:	03/09/2021	Nature of Claim:	TP
		Claim No:	1325742353SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHA5727D</b>		
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No:	D4FDGU674234
Reg. Date:	24/11/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU096426
Colour:	Blue	Odometer:	804830 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	206/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,046.52	711.00	2,335.52	76.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	1,120.00	570.00	33.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,736.52</b>	<b>1,831.00</b>	<b>2,905.52</b>	<b>61.34</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,450.00</b>		

(S\$)	4,736.52	1,450.00	3,286.52	69.39
<b>+ GST 7.00/7.00% (S\$)</b>	331.56	101.50	230.06	69.39
<b>Nett Amount (S\$)</b>	<b>5,068.08</b>	<b>1,551.50</b>	<b>3,516.58</b>	<b>69.39</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$110.67/day) (S\$)</b>		442.68		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,196.18</b>		

INSPECTION

Date of Assignment: 06/09/2021

Date Inspected: 06/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
 59 Loyang Drive  
 Singapore 508969

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH	Repair	663.00 FL	*- FL
2	1		*FRT DOOR MIRROR RH	Cracked	670.00 FL	*670.00 FL
3	1		*FRT DOOR RH	Repair	2,256.40 FL	*- FL
4	1		*FRT DOOR ADVERTISEMENT LOGO RH	Necessary	100.00 FS	*100.00 FS
5	1		*FRT DOOR COMFORT LOGO RH	Necessary	75.00 FS	*75.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	3,764.40845.00
					- List Item Discount on L Items 20.00/20.00% (\$)	717.88134.00
					Total Parts (\$)	3,046.52711.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	560.00
2	SPRAY PAINTING CHARGE	New	750.00	500.00
3	TRANSFER OF DOOR	New	120.00	0.00
4	TUFF KOTE	New	60.00	30.00
5	CHECK WIRING AND LIGHTIGN	New	60.00	30.00
Gross Labour Cost (S\$)			1,690.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >