

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref

305485597

Via Fax

EMAIL

Date

06.09.21

Your Insured

SKC 85J

Time of Fax

Date of Acc

03.09.21

Attn: Motor Claims Department

ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Ena

Tel: 6214 8355 or HP: 9824 0811

♦ Jumani Bin Masudin

Tel: 6214 8315 or HP: 9635 5305

♦ Lim Tien Siong

Tel: 6214 8398 or HP: 9635 8546

& Chiang Liat Choon

Tel: 6214 8314 or HP: 9296 6006

chianglc@cdge.com.sg Fax no. 6546 8156

If we do not hear from you within the <u>next 48 hours</u>, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH 8553B

03/09/21

MAKE REG. 30.10.2019
MODEL IONIQ G3

CHIANG/AIG

| MODEL | IONIQ G3 CHIANG/AIG | | | |
|-------|---|------|------------|------------|
| Qty | Parts Description/ Labour | Туре | Unit Price | Amount |
| 1 | REAR BUMPER | | | \$459.40 |
| 1 | REAR BUMPER CENTRE MOULDING | | | \$451.25 |
| 1 | REAR BUMPER REINFORCEMENT | | | \$394.80 |
| 2 | REAR BUMPER STAY LH /RH | | \$138.10 | \$276.20 |
| 1 | REAR BUMPER LOWER CENTRE MOULDING | | | \$155.00 |
| 10 | REAR BUMPER CLIPS | | \$2.20 | \$22.00 |
| 1 | BOOTLID COVER | | | \$2,480.40 |
| 1 | BOOTLID LOCK UPPER | | | \$224.00 |
| 1 | BOOTLID H EMBLEM | | | \$38.00 |
| 1 | BOOTLID EMBLEM IONID | | | \$31.80 |
| 1 | BOOTLID EMBLEM HYBRID | | | \$24.30 |
| 1 | BUMPER FOG LAMP | | | \$201.00 |
| 1 | BUMPER NUMBER LAMP LH/RH | | \$85.30 | \$170.60 |
| 1 | BUMPER HOOK COVER | | | \$94.60 |
| 1 | REAR REFLECTOR LH | | | \$41.45 |
| 1 | REAR ANTENNA – SMART KEY | | | \$40.50 |
| 2 | REAR BUMPER BRACKET LH /RH | | | \$55.80 |
| | | | | \$5,161.10 |
| | 20.00% | | | \$1,032.22 |
| | DISCOUNTED TOTAL | | | \$4,128.88 |
| | | | | |
| 1 | BOOTLID ADVERTISEMENT | | | \$100.00 |
| 1 | REAR BUMPER ADVERTISEMENT | | | \$100.00 |
| 1 | BOOTLID COMFORT APP STICKER | | | \$40.00 |
| 2 | BOOTLID COMFORT /TEL NUMBER STICKER | | \$30.00 | \$60.00 |
| 1 | REAR NUMBER PALTE W/HOLDER | | | \$55.00 |
| 1 | REAR REVERSE SENSOR | | | \$180.00 |
| | | | | \$535.00 |
| | | | | |
| | Labour Charge | | | |
| | Panel Beating | | | \$750.00 |
| | Spray Painting Charge | | | \$600.00 |
| | Check wiring and lighting | | | \$60.00 |
| Ì | Tuff Kote | | | \$60.00 |
| | Remove/Refix reverse sensor | | | \$60.00 |
| | TOTAL LABOUR | | | \$1,530.00 |
| | + | | | |
| * | ESTIMATE TOTAL | | | \$6,193.88 |
| l | | | | |
| | | | | |
| | | | | |
| | | | | |
| h | his is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will | | | |

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.