

Our Job Ref No : 305485597
Date : 11/09/21

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No : SH8553B

03/09/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: AIG SKC85J

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,789.44

(b) Labour Charges \$1,490.00

Total for Part-By-Part Repair Cost \$3,279.44

(c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : _____

Signature : 

Name : CHIANG

Name : Thevan

Tel : 62148314

Date : 14/9/21

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

03/09/21

MODEL IONIQ G3

CHIANG/AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER STAY LH /RH		\$138.10	\$276.20
1	REAR BUMPER LOWER CENTRE MOULDING			\$155.00
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	BOOTLID COVER			\$2,480.40
1	BOOTLID LOCK UPPER			\$224.00
1	BOOTLID H EMBLEM			\$38.00
1	BOOTLID EMBLEM IONID			\$31.80
1	BOOTLID EMBLEM HYBRID			\$24.30
1	BUMPER FOG LAMP			\$201.00
1	BUMPER NUMBER LAMP LH/RH		\$85.30	\$170.60
1	BUMPER HOOK COVER			\$94.60
1	REAR REFLECTOR LH			\$41.45
1	REAR ANTENNA - SMART KEY			\$40.50
2	REAR BUMPER BRACKET LH /RH			\$55.80
				\$5,161.10
				\$1,032.22
				\$4,128.88
1	BOOTLID ADVERTISEMENT			\$100.00
1	REAR BUMPER ADVERTISEMENT			\$100.00
1	BOOTLID COMFORT APP STICKER			\$40.00
2	BOOTLID COMFORT /TEL NUMBER STICKER		\$30.00	\$60.00
1	REAR NUMBER PALTE W/HOLDER			\$55.00
1	REAR REVERSE SENSOR			\$180.00
				\$535.00
	Labour Charge			
	Panel Beating			\$750.00
	Spray Painting Charge			\$600.00
	Check wiring and lighting			\$60.00
	Tuff Kote			\$60.00
	Remove/Refix reverse sensor			\$60.00
	TOTAL LABOUR			\$1,530.00
	ESTIMATE TOTAL			\$6,193.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Thuan @ Lth

82235769

thuan@lkhauto.com

3 days up

6/9/21 17:00:15

Pls bfr print pictures

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.