

KAIZENMOTORS

KAIZEN MOTORS PTE. LTD

68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896

UEN 201502816H GST Reg No 201502816H

Tel (+65) 6384 1956 Fax (+65) 6384 1957

Webpage <https://www.kaizenmotors.com.sg>



Date 03/09/2021
Vehicle No SLN7203U
Model Honda Vezel
Mileage

Accident Damaged Parts

No	Job Description	Qty	Price / Unit	Amount
1	REAR BUMPER <i>✓ ll</i>	1	\$ 1,278.48	\$ 1,278.48 751
2	REAR BUMPER BRACKET <i>✓ BR</i>	2	\$ 52.40	\$ 104.80 55.8
3	REAR BUMPER REFLECTOR <i>✓ ll</i>	2	\$ 216.35	\$ 432.70 141
4	REAR BUMPER SIDE GARNISH <i>✓ ll</i>	2	\$ 258.76	\$ 517.52 165.9
5	REAR REINFORCEMENT BEAM <i>✓ ll</i>	1	\$ 537.63	\$ 537.63 X
6	REAR TAILGATE <i>✓ ll</i>	1	\$ 1,386.38	\$ 1,386.38 953
7	REAR TAILGATE RUBBER MOULDING <i>✓ ll</i>	1	\$ 197.80	\$ 197.80 40(SN)
8	REAR TAILGATE DAMPER <i>✓ ll</i>	2	\$ 180.45	\$ 360.90 X
9	REAR TAILGATE INNER TRIMMING <i>✓ ll</i>	1	\$ 573.80	\$ 1,147.60 205.5
10	REAR TAILGATE LOWER LINING ASSY <i>✓ ll</i>	1	\$ 372.16	\$ 372.16 X
11	REAR END PANEL <i>✓ ll</i>	1	\$ 796.85	\$ 796.85 517
12	REAR END PANEL TRIMMING <i>✓ ll</i>	1	\$ 203.44	\$ 203.44 101.6
13	REAR SPARE TIRE WHEEL COMPARTMENT <i>✓ CRUMP</i>	1	\$ 1,223.25	\$ 1,223.25 917.6
14	REAR TAIL LAMP INNER <i>✓ CRA</i>	2	\$ 832.71	\$ 1,665.42 650
15	REAR TAIL LAMP OUTER <i>✓ CRA</i>	2	\$ 784.23	\$ 1,568.46 920.4
16	REAR FENDER <i>✓ ll</i>	2	\$ 1,379.36	\$ 2,758.72 X
17	REAR FENDER INNER TRIMMING <i>✓ ll</i>	1	\$ 669.08	\$ 669.08 240
18	REAR FENDER WHEEL GUARD GARNISH <i>✓ ll</i>	1	\$ 355.10	\$ 355.10 111.9
19	REAR HONDA EMBLEM <i>✓ ll</i>	1	\$ 70.44	\$ 70.44 31.9
20	REAR VEZEL EMBLEM <i>✓ ll</i>	1	\$ 70.44	\$ 70.44 56.2
21	REAR HYBRID EMBLEM <i>✓ ll</i>	1	\$ 101.80	\$ 101.80 64.1
22	REAR TAIL GATE LOCKING MECHANISM <i>✓ ll</i>	1	\$ 192.18	\$ 192.18 151.9
23	REAR TAIL GATE LOCKING PIN STRIKER <i>✓ ll</i>	1	\$ 70.40	\$ 70.40 27.5
24	REAR TAIL GATE LOCKING SWITCH <i>✓ ll</i>	1	\$ 262.14	\$ 262.14 X
25	REAR WIPER MOTOR <i>✓ ll</i>	1	\$ 418.34	\$ 418.34 X
26	REAR LICENCE PLATE LAMP COVER <i>✓ ll</i>	1	\$ 233.60	\$ 233.60 X
27	REAR LICENCE PLATE LAMP <i>✓ ll</i>	2	\$ 79.02	\$ 158.04 X
28	SPARE TIRE TOOL BOX SPONGE ASSY <i>✓ ll</i>	1	\$ 339.40	\$ 339.40 226.5
29	REAR LICENSE PLATE COVER <i>✓ ll</i>	1	\$ 50.00	\$ 50.00 20(SN)
30	REAR LICENSE PLATE <i>✓ ll</i>	1	\$ 50.00	\$ 50.00 X
31	REAR BUMPER CLIPS <i>✓ ll</i>	20	\$ 5.00	\$ 100.00 40(SN)
32	REAR TAIL LAMP CLIPS <i>✓ ll</i>	10	\$ 6.00	\$ 60.00 20(SN)
33	REAR TAILGATE TRIMMING CLIPS <i>✓ ll</i>	10	\$ 7.00	\$ 70.00 30(SN)
34	REAR TAILGATE SPOILER CLIPS <i>✓ ll</i>	10	\$ 7.00	\$ 70.00 X
35	REAR REVERSE SENSOR <i>✓ ll</i>	4	\$ 500.00	\$ 500.00 200(SN)
36	LABOUR FOR CHECKING ON WIRING		\$ 250.00	\$ 250.00 30
37	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF REAR END ASSY & PARTS		\$ 2,800.00	\$ 2,800.00 1000
38	SPRAYPAINTING & PUTTY OF REAR BUMPER, REAR BOOT REAR DIFFUSER, END PANEL, BUMPER GARNISH		\$ 1,800.00	\$ 1,800.00 1200
39	LABOUR FOR RETROFITTING MOULDING & SEAL		\$ 550.00	\$ 550.00 120
40	ALIGNMENT <i>✓ ll</i>		\$ 150.00	\$ 150.00 X

41	LABOUR FOR DIAGNOSING & RESETTING OF FAULT ON TAIL LAMP & PARKING SENSOR	\$	850.00	\$	850.00	40
40	TRANSFERRING OF TAILGATE PARTS TO NEW TAILGATE	\$	550.00	\$	550.00	60
41	APPLYING OF RUST PROOFING	\$	300.00	\$	300.00	80

Sub-Total	\$	25,643.07
GST 7%	\$	1,795.01
Grand Total	\$	27,438.08

75 Days.

~~8/8~~

before paint photos.

Guo Qiang
8288282

7/9/2021

6288.8

-20%: 5031.04

350

2530

310.25

-20%: 248.4

300

8459.44

-20%: 6750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: