

Veron Chen (LKKAuto)

From: Bryan Ang (LKKAuto)
Sent: Wednesday, 24 November 2021 12:03 PM
To: Veron Chen (LKKAuto)
Subject: RE: SDV 6668X---CS3/ASM21009350/Bvc

Hi

Parts found not replaced for both rear exhausts.

No photos of some parts. Engine mounting, engine mounting brackets, lift up engine and transmission.

For the damage to the gearbox, the after repair seems like not changed. For example no photo of damaged and replaced part together during the after repair to justify the replacement for big ticket item. Suggest to allow repair work for the housing which can be adjusted at the labour section from 600 to 1000

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Sent: Wednesday, 24 November 2021 10:25 AM

To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Subject: SDV 6668X---CS3/ASM21009350/Bvc

Dear Bryan

File for audit check.-**urgent**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)