

ESTIMATE REPAIR COST

AT PERFORMANCE160 SIN MING DRIVE #07-19 SIN MING
AUTOCITY SINGAPORE 575722

TEL: 6453 5112

FAX: 6552 2061

Messrs. Seow Pak Khoo Raymond
4 Jalan Sembilang
Singapore 576864

Date 08/09/21

Vehicle No. SDV6668X PORSCHE 987 BOXTER S TIPTRONIC

2007

Quantity	Items/Descriptions	Prices
1PC	LH TAILLAMP ASSY.	BR✓ 654.70 545.38
1PC	RH TAILLAMP ASSY.	BR✓ 654.70 545.38
1PC	REAR BUMPER ASSY	BR✓ 1995.01 1860.60
1PC	REAR BUMPER REINFORCEMENT	BR✓ 614.03 ✓
1PC	REAR BUMPER REINFORCEMENT ALUMINIUM COVER	BT✓ 164.12 ✓
1PC	REAR BUMPER CENTER BEAM	DP✓ 198.90 ✓
2PCS	REAR BUMPER SIDE SUPPORT BRACKETS @ \$344.15/PC - 206.70	DD✓ 688.30 413.40
1PC	REVERSE CAMERA UNIT	SC✓ 350.00 ✓
4PCS	REVERSE SENSORS @ \$403.98/PC 280.00	SC✓ 1615.92 1120.00
1PC	REVERSE SENSOR HARNESS ASSY	CT✓ 325.11 ✓
1PC	REAR NUMBER PLATE	BR✓ 40.00 25.00
2PCS	REAR NUMBER PLATE LAMPS @ \$63.01/PC	BR✓ 126.02 ✓
2PCS	REAR BUMPER EXHAUST PIPE GARNISHES @ \$353.94/PC - 226.00	DD✓ 707.88 452.00
1PC	RH REAR EXHAUST PIPE ASSY	5253.60 } NCX
1PC	LH REAR EXHAUST PIPE ASSY	5253.60 }
1SET	EXHAUST MOUNTING	1157.70 165.00
1SET	EXHAUST MOUNTING BRACKETS	NEC✓ { 63.92 ✓
1PC	EXHAUST CONNECTOR C/W TAIL CHROME PIPES	DD✓ 1339.10 ✓
1PC	REAR EXHAUST PIPE ALUMINIUM HEAT SHIELD	DD✓ { 184.25 140.00
1PC	BOOT FLOOR PANEL HEAT INSULATOR	569.41 458.00
1PC	AUTO TRANSMISSION GEARBOX ASSY	BRXR 41067.11 RX
1PC	AUTO TRANSMISSION GEARBOX MOUNTING BRACKET ASSY	NEC✓ 513.90 ✓
Total C/fd		\$64,337.28

for **AT PERFORMANCE**

ESTIMATE REPAIR COST

AT PERFORMANCE

160 SIN MING DRIVE #07-19 SIN MING
AUTOCITY SINGAPORE 575722


TEL: 6453 5112

FAX: 6552 2061

Messrs. Seow Pak Khoo Raymond Date 08/09/21
4 Jalan Sembilang
Singapore 576864

Vehicle No. SDV6668X PORSCHE 987 BOXTER S TIPTRONIC

Quantity	Items/Descriptions	Prices
	Bal B/fd:	64337.28
2PCS	ENGINE MOUNTINGS @\$594.06/PC	1188.12 } NNX
2PCS	ENGINE MOUNTING BRACKETS @680.49/PC	1360.98 }
1PC	REAR TORSION BAR	✓ 615.43 BTV
1PCC	REAR STABILIZER BAR	✓ 507.73 BTV
2PCS	REAR STABILIZER BAR LINKS @ ^{231.00} \$253.12/PC	506.24 BTV
2PCS	REAR STABILIZER BAR BRACKETS @\$13.06/PC	✓ 26.12 DDV
2PCS	REAR FENDER SPLASH SHIELDS @\$82.20/PC	✓ 164.40 BRV
1PC	DASHBOARD LH GLOVE BOX ASSY	2293.25 NNX
1PC	DASHBOARD CENTRE AUDIO/VIDEO	800.00 } DLXR
1PC	DASHBOARD CENTRE CUP HOLDER	994.66 }
	10862.06 @ 10% 1086.21 9775.85	
	Towing (Twice)	100.00 ✓
	Renew exhaust pipe system	200.00 ✓
	Lift out engine with transmission assy	1000.00 ✓
	Renew transmission assy	600.00 ✓
	Total:	\$75,894.21


for **AT PERFORMANCE**

ESTIMATE REPAIR COST

AT PERFORMANCE

160 SIN MING DRIVE #07-19 SIN MING
AUTOCITY SINGAPORE 575722

TEL: 6453 5112

FAX: 6552 2061

Messrs. Seow Pak Khoo Raymond
4 Jalan Sembilang
Singapore 576864

Date 08/09/21

Vehicle No. SDV6668X PORSCHE 987 BOXTER S TIPTRONIC

Quantity	Items/Descriptions	Prices
	Bal B/fd:	75894.21
	Electrical system	250.00
	Renew reverse camera unit	200.00 ✓
	Renew reverse sensors	200.00 ✓
	Panel Beating	1000.00 ✓
	Body Alignment on Chassis Alignment System *	* 1000.00
	Spray painting	300.00 ✓
	Diagnostic programming and calibration	500.00
	* To provide complete wheel alignment and body alignment report before amendment can be made	3470
Total:		\$79,344.21

Survey 7/9/2021
1442hrs
Terima Min

Resurvey 10/9/2021
1310hrs
Terima Min

Lump sum repair
Repair days 24

for AT PERFORMANCE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Parts 9,775.85
S/N -
Labour 3470.00
13,245.85
@20% 2649.17
10596.68

LS 10,600/2

NV 46,089/2