



## Re: Re:IA SUBMITTED FOR SDV 6668X

Type

Question

Message

Dear Hsiao Tong, can please assist to get oyur surveyor to re-assess the adjustment as we noted that your resurvey photo shows that TP's gear box cracked but it's not included in the adjustment report, thanks

11/5 submit preli report LS 10,600 (un-confirmed), 34 days

Reply

P —

Survey who inspected since no longer with  
1Kk.

~~Suggest to~~ <sup>after rep</sup> From the photos, the gear box

Seems to be not changed. Suggest to request  
for a physical re-inspection - if possible to verify  
the replacement due to the high cost of this item.

Note also that Independent ~~Survey~~ <sup>Survey report</sup>  
did not contain any other photos.