

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Rea. No: 199607198R GST Rea. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21009354/Auf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	30/09/2021	
			Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJZ 2390E	Veh. Inspected	SML 2901U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10011564/CD	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	06/09/2021	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ CLA180	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	WDD1173422N764387	Colour	GREY	
	Odometer	37929 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
	L/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
	R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
	L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/09/2021	Inspection Date	07/09/2021	
	Survey held at	LEANG AUTOMOTIVE			
		BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: