

SML 29014. 2019 May.
Mercedes Benz C180. 1595 cc.
WDD1173422N764387

TP Budget Direct.
Huizhen.

hist: 2751
Len 10%: 2475.50
S.N: 30

Labour: 480

Total: 2985.50

2/S: 2350

02 Days.

Rees Bumper Deformed	1635	✓
Rees Bumper Clips. New	50(SN) ^{30(SN)}	
Rees Bumper Side Holder x 2	79 x 2 = 158	X
Rees Bumper lower Garnish. Deformed	406.	✓
Rees Bumper lower Garnish Chrome Moulding	286	✓
Rees Bumper Reinforcement	655	X
Rees Bumper Centre Guide cracked	159	✓
Reverse Sensor x 04	265 x 4 = 1060	
Rees End Panel. Rep's	1290.	X

Panel Beating

Spray Painting

Wiring.

~~800~~ 200

~~800~~ 200

~~50~~ 30

~~100~~ 50.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total \$6168.60