



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2202892

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 19/05/2022
Reference CC4/LPC21009355/Bea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJN 8866Z
Insured Veh. GBC 4326U
Claim No. 20/21/21/VC05/024917
Policy No. Z20VC05006146
Accident Date 27/08/2021
Inspection Date 07/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21009355/Bea3q2 Date: 19/05/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBC 4326U	Veh. Inspected	SJN 8866Z
	Policy No.	Z20VC05006146	Coverage (\$)	0.00
	Claim No.	20/21/21/VC05/024917	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	06/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ S350	c.c	3498
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	WDD2211562A174717	Colour	BLACK
	Odometer	80101 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R17	MICHELIN	5 mm
	L/H Front Tyre	235/55 R17	MICHELIN	5 mm
	R/H Rear Tyre	235/55 R17	MICHELIN	5 mm
	L/H Rear Tyre	235/55 R17	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/08/2021	Inspection Date	07/09/2021
	Survey held at	ACCIDENT ASSIST SG 24 SIN MING LANE, #01-94, MIDVIEW CITY, SINGAPORE 573970		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 8866Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	DENTED	2,986.00	2,042.70
1	BOOTLID WEATHERSTRIP	NOT DAMAGED	420.00	-
1	BOOTLID INNER LOCK	JAMMED	485.00	309.60
1	BOOTLID LOGO	NECESSARY	145.00	48.00
1	BOOTLID EMBLEM 'S350'	NECESSARY	112.00	81.60
1	BOOTLID OUTER GARNISH CHROME	NOT DAMAGED	220.00	-
2	TAILLAMP @\$1186.00	N/S BROKEN	2,372.00	723.00
2	TAILLAMP LOWER BRACKET @\$166.00	NOT DAMAGED	332.00	-
2	SET TAILLAMP OUTER GARNISH @\$190.00	NOT DAMAGED	380.00	-
1	REAR BUMPER	DENTED	2,245.00	1,850.00
2	REAR BUMPER SIDE RETAINER @\$138.00	NECESSARY	276.00	160.00
2	REAR BUMPER SIDE BRACKET @\$142.00	NO SUCH PARTS	284.00	-
1	REAR BUMPER CENTRE BRACKET	NOT NECESSARY	295.00	-
1	REAR BUMPER REINFORCEMENT	DENTED	859.00	650.00
4	REAR BUMPER SENSOR (ORI) @\$460.00	SCRATCHED (2 PCS ONLY)	1,840.00	450.00
1	SET REAR BUMPER SENSOR RING	NECESSARY	145.00	50.00
1	REAR BUMPER TOW COVER	NOT DAMAGED	78.00	-
1	REAR END PANEL	DENTED	1,208.00	933.00
1	REAR END PANEL TOP GARNISH	BROKEN	417.00	126.00
1	REAR SPARE TYRE WELL	NOT DAMAGED	1,486.00	-
1	REAR SPARE TYRE TOP BOARD	NOT NECESSARY	385.00	-
	LESS 10% DISCOUNT		-1,697.00	-742.39
			15,273.00	6,681.51
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	BOOTLID SEALANT (SN)	NOT NECESSARY	100.00	-
2	SET TAILLAMP CLIPS (SN)	N/S NECESSARY	70.00	20.00
2	TAILLAMP SEAL (SN)	N/S NECESSARY	65.00	20.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	30.00

Report Ref No. CC4/LPC21009355/Bea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	55.00	30.00
1	REAR SPARE TYRE WELL SEALANT (SN)	NOT NECESSARY	100.00	-
			650.00	130.00
	LABOUR			
	PANEL BEATING AND STRENGTHEN PARTS ON REAR ACCIDENT AREA .		1,500.00	600.00
	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNET.	NOT NECESSARY	80.00	-
	R&R INTERIOR UPHOLSTERY .	NOT NECESSARY	200.00	-
	TO APPLY UNDERCOATING FOR RUST ROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING ON REAR ACCIDENT AREA.		1,000.00	400.00
			2,980.00	1,000.00
GRAND TOTAL			18,903.00	7,811.51

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,250.00
---	--	--	--	-----------------

Report Ref No. CC4/LPC21009355/Bea3q2

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJN 8866Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

