

Accident Assist SG

24 Sin Ming Lane #01-94 Midview City Singapore 573970

Tel: 6334 1182 Email: management@assist.com

Registration no. : SJN8866Z / Mercedes Benz S350 L A

Date : 03-Sep-21

Estimate No. : AAS006_SJN8866Z_S350

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Bootlid	2086.00	DD✓
2	1	Bootlid weatherstrip	420.00	NDX
3	1	Bootlid inner lock	485.00	JMV
4	1	Bootlid logo	145.00	} NEC
5	1	Bootlid emblem 'S350'	112.00	
6	1	Bootlid outer garnish chrome	220.00	NDX
7	1/2	Taillamp @ SGD 1186.00 723.00	2372.00	BR✓
8	2	Taillamp lower bracket @ SGD 166.00	332.00	NDX
1	2set	Taillamp outer garnish @ SGD 190.00	380.00	NDX
2	1	Rear bumper	2245.00	DD✓
3	2	Rear bumper side retainer @ SGD 138.00	276.00	NECV
4	2	Rear bumper side bracket @ SGD 142.00	284.00	NSX
5	1	Rear bumper centre bracket	295.00	NNX
5	1	Rear bumper reinforcement	859.00	DD✓
7	2/4	Rear bumper sensor (ORI) @ SGD 460.00 225.00	1840.00	SCV
8	1set	Rear bumper sensor ring	145.00	NECV
1	1	Rear bumper tow cover	78.00	NDX
2	1	Rear end panel	1208.00	DD✓
3	1	Rear end panel top garnish	417.00	BR✓
4	1	Rear spare tyre well	1486.00	NDX
5	1	Rear spare tyre top board	385.00	NCLX
			7,423.90	16970.00
			Less 10%	742.39
			6681.51	15273.00

SPECIAL NETT ITEMS

1	1	Sundries	80.00	NNX
2	1	Bootlid sealant	100.00	NNX
3	2set	Taillamp clips LH	20.00	NECV
4	1/2	Taillamp seal LH	20.00	NECV
5	1set	Rear bumper clips	30.00	NECV
6	1	Rear end panel sealant	30.00	NECV
7	1set	Rear end panel top garnish clips	30.00	NECV
8	1	Rear spare tyre well sealant	100.00	NNX
			130.00	650.00

PART TOTAL

17620.00

Accident Assist SG

24 Sin Ming Lane #01-94 Midview City Singapore 573970

Tel: 6334 1182 Email: management@assist.com

Registration no. : SJN8866Z / Mercedes Benz S350 L A
Date : 03-Sep-21 Estimate No. : AAS006_SJN8866Z_S350

S/N	Qty	Item	Amount
-----	-----	------	--------

LABOUR & MISC CHARGES

1	1	Panel beating and strengthen parts on rear accident area.	600.00	1500.00	✓
2	1	Check wiring system after disconnect and connect.		80.00	NXX
3	1	R&R interior upholstery.		200.00	} NXX
4	1	To apply undercoating for rust roofing.		200.00	
5	1	Spray painting on rear accident area.	400.00	1000.00	✓
LABOUR TOTAL			1,000.00	2980.00	

Total Parts and Labour Cost of Repair			20600.00
---------------------------------------	--	--	----------

Survey 7/9/2021 1254 hrs TGU in Min
Resurvey 8/9/2021 1512 hrs TGU in Min
Lump Sum repair Repair days 5

Parts 6,681.51
SN 130.00
Labour 1,000.00
7,811.51
@ 20% 1,562.30
6249.21

LS 6,250/2

LEK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: