

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 14/09/2021

User ID PohSuan

Section A - Accident Details

Registration Number	SHC4790R
Case Reference Number	TAX/09/21/2002
Registration Date	1/4/2016
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	FAROUKH BIN DAWOOD
Type of Accident	Head to Rear
Accident Date and Time	2/9/2021 7:30 AM
Accident Reported Date and Time	2/9/2021 3:40 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112150
Special Instruction to ARC, if any	TP / REAR PORTION
Prepared Date and Time	2/9/2021 5:42 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$3,744.12	\$166.86
Total Other Cost	\$360.00	\$20.00
TOTAL COST	\$5,349.12	\$586.86
Lump Sum Total	\$5,350.00	\$600.00 (L/S)
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	GUO QIANG (LKK) / China Taiping
ARC / Surveyor Sign Off Date	07/09/2021 10:19 AM	07/09/2021 10:12 AM
Signature		
Remarks	Total number of repair days = 2 days. SUP = 0 day.	lump sum repair / after repair photo.

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/09/2021

User ID PohSuan

		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
		81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given	X
		81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given	X
Total					\$4,430.10		\$120.00			

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace	√
Total					118.10		88.58			

	208.58	
	-20%	L/S \$600/-
	166.86	
+	200.00	
+	220.00	
	586.86	