

## **LKK Auto Consultants Pte Ltd**

LKK Auto Consultants Pte L 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 7349E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR LH	BUCKLED	851.10	851.10
1	FRONT DOOR GLASS OUTER MOULDING LH	SERVICEABLE	58.00	-
1	FRONT DOOR OUTER HANDLE LH	SERVICEABLE	85.00	-
1	FRONT DOOR INNER LOCK LH	TO REPAIR SEE LABOUR	233.70	-
1	FRONT DOOR OUTER GARNISH VERTICAL LH	NECESSARY	36.00	36.00
1	FRONT DOOR WINDOW REGULATOR C/W MOTOR LH	SERVICEABLE	405.30	-
1	FRONT DOOR WINDOW CHANNEL LH	SERVICEABLE	68.80	-
1	REAR DOOR OUTER MOULDING LH	SERVICEABLE	53.30	-
1	REAR DOOR CHECKER LH	SERVICEABLE	74.50	-
1	REAR DOOR INNER LOCK LH	TO REPAIR SEE LABOUR	231.20	-
1	REAR DOOR GARNISH VERTICAL REAR LH	NOT NECESSARY	30.00	-
	LESS 20% DISCOUNT		-	-177.42
			2,126.90	709.68
	SPECIAL NETT ITEMS			
1	REAR DOOR LH (SN) (LOCAL REPAIR)	BUCKLED	865.00	150.00
1	FRONT DOOR SPEAKER LH (SN)	SERVICEABLE	150.00	-
			1,015.00	150.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEATING AND REAR LH FENDER, CENTRE PILLAR LH AND LH FRAME MEMBERS. TO REMOVE, TRANSFER AND REFIT LH FRONT AND REAR DOOR COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR INNER LOCK LH AND REAR DOOR INNER LOCK LH.		900.00	400.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		840.00	440.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO RUST PROOF AFFECTED AREAS.		120.00	30.00
			1,940.00	890.00
	GRAND TOTAL		5,081.90	1,749.68

Report Ref No. CS3/SMO21002097/Kvf3e2-1



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,400.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/SMO21002097/Kvf3e2-1

**KONG SENG CHEONG** 

**Licensed Appraiser**