

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Xiao Tony

Quotation

DATE : 07.09.2021
 VEH NO : GBC2405M
 MODEL : Nissan NV200
 D O A : 03.09.2021
 YR REF : SNA2399R

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBC2405M (NISSAN NV200)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Dehd.</i>	1	632.70 ✓
2	Rear Bumper Side Holder - LH & RH <i>new</i>	2	70.80 ✓
3	Rear Bumper Reflector - LH & RH <i>new</i>	2	122.00 X
4	Rear Bumper Sponge <i>crushed</i>	1	145.20 ✓
5	Rear End Panel - Outer <i>Dented.</i>	1	366.20 ✓
6	Rear End Panel - Inner <i>Dented</i>	1	610.80 ✓
7	Rear End Panel Top Garnish <i>Dehd</i>	1	129.10 ✓
8	Tail Lamp - LH <i>new</i>	1	297.40 X
9	Rear Door - LH <i>Dented</i>	1	1,469.60 ✓
10	Rear Door Lower Lock - LH <i>Dented</i>	1	135.60 ✓
11	Rear Door Weatherstripe - LH <i>cut</i>	1	136.70 ✓
12	Nissan Logo <i>new</i>	1	85.00 ✓
13	NV200 Emblem <i>new</i>	1	88.40 ✓
			4,289.50
Less <i>10%</i> 20%			(857.90)
			<u>\$ 3,431.60</u>

3870.10

3483.09

S/NETT ITEMS

1	Rear Bumper Clips <i>new</i>	1 set	\$ 30.00 ✓
2	Rear Bumper Centre Protector - LH & RH <i>new</i>	2	\$ 100.00 ✓
3	Reverse Sensor <i>Dented</i>	1	\$ 280.00 <i>200.</i>
4	Rear End Panel Sealant <i>new</i>	1	\$ 60.00 ✓
5	Rear Door Reflective Sticker - LH <i>new</i>	1	\$ 80.00 <i>20.</i>
6	Rear Door Glass Sealant - LH <i>new</i>	1	\$ 50.00 ✓
7	70km/h sticker <i>new</i>	1	\$ 15.00 ✓
			<u>\$ 615.00</u>

475

RE : ESTIMATE FOR ACCIDENT REPAIR GBC2405M (NISSAN NV200)

Total Parts		\$	4,046.60
<u>LABOUR CHARGE - REAR PORTION</u>			
1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 1000.
2	To putty & spray up paint works	\$	800.00 750.
3	To check wiring	\$	50.00 30
4	To remove reverse sensor	\$	100.00 50
5	To remove upholstery	\$	150.00 80
6	To transfer door fittings	\$	150.00 80
7	To remove rear door glass	\$	100.00 60.
Total Labour		\$	2,550.00
Grand Total		\$	6,596.60

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: ~~6008.09~~
H/S: 4.8K.
OT Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: