



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2204451

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 20/07/2022
Reference CC4/LPC21009376/Bea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBC 3099G
Insured Veh. GBK 8097L
Claim No. 20/21/21/VC05/024927
Policy No. Z20VC05006605
Accident Date 31/08/2021
Inspection Date 09/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21009376/Bea3q2 Date: 20/07/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 8097L	Veh. Inspected	GBC 3099G	
Policy No.	Z20VC05006605	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024927	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	06/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150 M	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JTFAT35Y70K201806	Colour	WHITE	
Odometer	391618 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	APLUS	6 mm	
L/H Front Tyre	195 R15	APLUS	6 mm	
R/H Rear Tyre	155 R12	CST	6 mm	
L/H Rear Tyre	155 R12	CST	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/08/2021	Inspection Date	09/09/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 3099G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH TAILLAMP ASSY	BROKEN	285.00	145.20
1	LH TAILLAMP ASSY	BROKEN	285.00	145.20
1	REAR NUMBER PLATE BRACKET	BENT	148.70	148.70
1	SPARE TYRE CARRIAGE	BENT	325.70	283.10
1	REAR NUMBER PLATE LAMP	MISSING	68.70	68.70
	LESS 25% DISCOUNT		-278.28	-197.73
			834.82	593.17
	<u>SPECIAL NETT ITEMS</u>			
1	ALUMINIUM BOX REAR RH DOOR (SN)	DENTED	1,800.00	1,800.00
1	ALUMINIUM BOX REAR RH DOOR OPEN/CLOSED ROD (SN)	BENT	650.00	400.00
1	ALUMINIUM BOX REAR RH DOOR OPEN/CLOSED ROD LATCH (SN)	NOT NECESSARY	220.00	-
1	ALUMINIUM BOX REAR RH DOOR OPEN /CLOSED ROD LOWER HOLDER (SN)	NOT NECESSARY	145.00	-
1	ALUMINIUM BOX REAR RH DOOR OPEN/CLOSED ROD CENTRE HOLDER (SN)	NOT NECESSARY	65.00	-
1	ALUMINIUM BOX REAR RH DOOR LATCH HOLDER (SN)	NOT NECESSARY	48.00	-
1	ALUMINIUM BOX REAR RH DOOR LOWER HINGE (SN)	NOT NECESSARY	280.00	-
1	ALUMINIUM BOX REAR RH DOOR OPEN/CLOSED ROD HANDLE (SN)	NOT DAMAGED	180.00	-
1	ALUMINIUM BOX REAR RH DOOR OPEN/CLOSED ROD HANDLE BRACKET (SN)	NOT DAMAGED	80.00	-
1	ALUMINIUM BOX REAR LH DOOR (SN)	DENTED	1,800.00	1,800.00
1	ALUMINIUM BOX REAR LH DOOR '70KMH/' STICKER (SN)	NECESSARY	40.00	20.00
1	ALUMINIUM BOX REAR LH DOOR LATCH HOLDER (SN)	NOT NECESSARY	48.00	-
1	SET REAR REVERSE SENSOR (SN)	SCRATCHED	280.00	200.00
1	REAR NUMBER PLATE (SN)	BENT	60.00	25.00
			5,696.00	4,245.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE, CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING ,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS.		1,000.00	400.00

Report Ref No. CC4/LPC21009376/Bea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON AFFECTED PANELS.	NOT NECESSARY	600.00	-
	CHECK ALL WIRING AND ALL LIGHTING SYSTEM.	NOT NECESSARY	80.00	-
	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS.	NOT NECESSARY	50.00	-
	REMOVE AND REPLACE REAR REVERSE SENSORS TO ASSIST REPAIR.		100.00	60.00
			1,830.00	460.00
GRAND TOTAL			8,360.82	5,298.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CC4/LPC21009376/Bea3q2

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 3099G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 3099G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

