

BIFROST AUTO PTE LTD**8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875**

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

EstimateVehicle No:
Model and make:GBC3099G
Toyota Dyna

2011

Qty Spare partsList price

- 1 RH taillamp assy
- 1 LH taillamp assy
- 1 Rear number plate bracket
- 1 Spare tyre carriage
- 1 Rear number plate lamp

\$ 145.20	285.00	BR ✓
\$ 145.20	285.00	BR ✓
\$	148.70	BT ✓
\$ 283.10	325.70	NDX BT
\$	68.70	MIS ✓

\$ 790.90	1,113.10
25% \$ 197.73	278.28
\$	834.83
593.18	

Qty Spare partsSpecial Nett price

- 1 Aluminium box rear RH door
- 1 Aluminium box rear RH door open/closed rod
- 1 Aluminium box rear RH door open/closed rod latch
- 1 Aluminium box rear RH door open/closed rod lower holder
- 1 Aluminium box rear RH door open/closed rod centre holder
- 1 Aluminium box rear RH door latch holder
- 1 Aluminium box rear RH door lower hinge
- 1 Aluminium box rear RH door open/closed rod handle
- 1 Aluminium box rear RH door open/closed rod handle bracket
- 1 Aluminium box rear LH door
- 1 Aluminium box rear LH door "70km/h" sticker
- 1 Aluminium box rear LH door latch holder
- 1 Rear reverse sensor (set)
- 1 Rear number plate

\$	✓ 1,800.00	DDV ✓
\$ 400.00	650.00	BT ✓
\$	220.00	NNX
\$	145.00	NNX
\$	65.00	} NNX
\$	48.00	
\$	280.00	NNX
\$	180.00	} NDX
\$	80.00	
\$	✓ 1,800.00	DDV ✓
\$ 20.00	40.00	NE ✓
\$	48.00	NNX
\$ 200.00	280.00	SC ✓
\$ 25.00	60.00	BT ✓

4245.00

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 400.00	1,000.00	✓
-----------	----------	---

Spray painting on affected panels

\$	600.00	NNX
----	--------	-----

Check all wiring and all lighting system

\$	80.00	NNX
----	-------	-----

Apply rust coating chemical on affected panels

\$	50.00	NNX
----	-------	-----

Remove and replace rear reverse sensors to assist repair

\$ 60.00 -100.00

460.00

\$ 8,360.83

Survey & Resurvey
on
9/9/2021

1500 hrs
TCUim

Lump sum repair
Repair days 5

Parts	593.18
SN	4245.00
Labour	460.00
	5298.18
@ 20%	1059.64
	4238.54

L/s 4250/-

TCUim
29/10/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: