



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2200647

INV Date 07/02/2022

Reference CC4/LPC21009383/Egs3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLB 1020H
Insured Veh. SLW 2745H
Claim No. 21/21/21/VP05/024920
Policy No. Z21VP05028531
Accident Date 01/09/2021
Inspection Date 07/09/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21009383/Egs3q2 Date: 07/02/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 2745H	Veh. Inspected	SLB 1020H	
Policy No.	Z21VP05028531	Coverage (\$)	0.00	
Claim No.	21/21/21/VP05/024920	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	07/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WWZZZAUZGW053450	Colour	BLUE	
Odometer	94108 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R16	PIRELLI	5 mm	
L/H Front Tyre	225/55 R16	PIRELLI	5 mm	
R/H Rear Tyre	225/55 R16	PIRELLI	5 mm	
L/H Rear Tyre	225/55 R16	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/09/2021	Inspection Date	07/09/2021	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			23 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 1020H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MOULDING HEADLINING PEARL ROOFLINING (SN)	CRUSHED	1,092.49	546.25
4	CLAMP (SN)	NECESSARY	5.12	2.56
1	HEAD AIRBAG UNIT SIDE CURTAIN AIRBAG RH (SN)	BROKEN	1,518.87	759.44
1	GRAB HANDLE FOLDING PEARL RHS ROOF TOP HANDLE FRT (SN)	NECESSARY	96.72	48.36
1	ROOF GRAB HANDLE PEARL GR RHS ROOF TOP HANDLE REAR (SN)	NECESSARY	101.32	50.66
2	TRIM WITH EMBLEM PEARL GR (SN)	NECESSARY	32.68	16.34
1	LINING PILLAR B TITANIUM RHS B-PILLAR TRIM (LOWER) (SN)	CRUSHED	179.74	89.87
1	SCUFF PLATE SILL PANEL TI RHS INNER SCUFF PLATE (SN)	NECESSARY	71.17	35.59
1	THREE -POINT AUTOMATIC SEA LHS FRT SEAT BELT (SN)	JAMMED	736.51	368.26
1	THREE -POINT AUTOMATIC SEA RHS FRT SEAT BELT (SN)	JAMMED	736.51	368.26
2	BOLT WITH POLYGON SOCKET (SN)	NECESSARY	13.22	6.61
2	SOCKET HD.SCREW WITH POL (SN)	NECESSARY	13.40	6.70
2	SOCKET HD.SCREW WITH POL (SN)	NECESSARY	13.22	6.61
2	SEAT BELT HEIGHT ADJUSTER (SN)	NECESSARY	230.42	115.21
2	BOLT (SN)	NECESSARY	7.98	3.99
1	BACKREST COVER (SN)	TORN	1,673.68	836.84
1	PDDING FOR BRACKET (SN)	BROKEN	242.43	121.22
1	SIDE AIR BAG UNIT RHS FRT SEAT AIRBAG (SN)	BROKEN	1,450.33	725.17
1	AIR BAG CONTROL MODULE AIRBAG CONTROL UNIT (SN)	NOT NECESSARY	1,245.73	-
1	DRUCKSENSOR RHS FRT DOOR AIRBAG SENSOR (SN)	NECESSARY	173.92	86.96
1	FENDER RHF FENDER (SN)	NOT NECESSARY	629.40	-
4	RIVETTED CAP NUT (SN)	NOT NECESSARY	10.00	-
1	DOOR RHF DOOR (SN)	DENTED	1,987.16	993.58
1	DOOR SEAL (SN)	NECESSARY	107.32	53.66
1	SOUND ABSORBER LAMINTED DOOR INSULATOR (SN)	NECESSARY	43.65	21.83
1	DOOR SEAL INNER RHF DOOR INNER SEAL (SN)	CRUSHED	202.30	101.15

Report Ref No. CC4/LPC21009383/Egs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BOLT WITH POLYGON SOCKET (SN)	NECESSARY	10.34	5.17
2	NUT (SN)	NECESSARY	2.90	1.45
1	DOOR LATCH RHF DOOR LOCK (SN)	JAMMED	399.55	199.78
2	FILL .HD.SCREW (SN)	NECESSARY	5.52	2.76
1	PLUG (SN)	NECESSARY	0.57	0.29
1	CAP SATIN BLACK (SN)	NECESSARY	3.73	1.87
1	HEX SOCKET HEAD LOCATING (SN)	NECESSARY	1.78	0.89
1	BOW SUPPORT DOOR HANDLE (SN)	NOT NECESSARY	127.96	-
1	WINDOW REGULATOR WITHOUT (SN)	NOT NECESSARY	426.71	-
1	WOOFER RHS FRT DOOR SPEAKER (SN)	NOT NECESSARY	80.82	-
8	POP-RIVET (SN)	NECESSARY	4.24	2.12
3	GROMMET (SN)	NECESSARY	5.10	2.55
3	CLIP (SN)	NECESSARY	5.13	2.57
1	DOOR TRIM PANEL RHF DOOR BOARD (SN)	NOT NECESSARY	690.34	-
6	CLIP (SN)	NECESSARY	9.78	4.89
1	SIDE PANEL RHS A-B PILLAR (SN)	NOT NECESSARY	2,580.16	-
1	2K-FULLSCHAUM (SN)	NOT NECESSARY	154.20	-
1	SEALANT CAN BE SPRAYED (SN)	NOT NECESSARY	64.23	-
1	ZINC SPRAY (SN)	NOT NECESSARY	68.87	-
1	2K-BODY ADHESIVE (SN)	NOT NECESSARY	444.39	-
1	LONG-LIFE UNDERSEAL (SN)	NOT NECESSARY	87.64	-
1	PILLAR B INNER RHS PILLAR INNER PANEL (OUTER) (SN)	NOT NECESSARY	1,187.53	-
1	REINFORCEMENT FOR PILLAR RHS B-PILLAR INNER PANEL (CTR) (SN)	NOT NECESSARY	433.46	-
1	PILLAR B INNER RHS B-PILLAR INNER PANEL (INNER) (SN)	NOT NECESSARY	1,117.42	-
1	STICKER STICKER (TYRE PRESSURE) (SN)	NOT NECESSARY	15.84	7.92
1	TIRE PRESSURE LABEL (SN)	NECESSARY	14.08	7.04
1	IDENLIFICATION PLATE STICKER (CHASSIS NO) (SN)	NECESSARY	529.83	264.92
1	DOOR RHS REAR DOOR (SN)	NOT NECESSARY	2,147.19	-
1	DOOR SEAL OUTER (SN)	NECESSARY	107.32	53.66
1	SOUND ABSORBER LAMINATED DOOR INSULATOR (SN)	NECESSARY	43.65	21.83
1	DOOR HINGE UPPER (SN)	NOT NECESSARY	142.59	-

Report Ref No. CC4/LPC21009383/Egs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HINGE LOWER (SN)	BENT	142.59	71.30
2	BOLT WITH POLYGON SOCKET (SN)	NECESSARY	10.34	5.17
4	HEX BOLT WITH INTERNAL TO (SN)	NECESSARY	14.36	7.18
2	NUT (SN)	NECESSARY	2.90	1.45
1	CHECK ROD DOOR (SN)	NOT NECESSARY	74.04	-
1	DOOR SEAL INNER (SN)	NECESSARY	88.44	44.22
1	DOOR LATCH DOOR LOCK (SN)	NECESSARY	383.00	191.50
2	FILL HD .SCREW (SN)	NECESSARY	5.52	2.76
1	LOCKING CATCH RH REAR DOOR LATCH (SN)	NOT NECESSARY	58.37	-
1	PLUG (SN)	NECESSARY	5.11	2.56
1	BOW RHR DOOR HANDLE SUPPORT (SN)	NOT NECESSARY	110.36	-
1	GLASS CHANNEL BLACK RHR DOOR CHANNEL SEAL (SN)	TORN	249.15	124.58
1	WINDOW REGULATOR (SN)	NOT NECESSARY	434.98	-
1	DOOR TRIM PANEL RHR DOOR BOARD (SN)	NECESSARY	674.49	337.25
6	CLIP (SN)	NECESSARY	9.78	4.89
1	CLIP (SN)	NECESSARY	1.63	0.82
1	WOOFER RH REAR DOOR SPEAKER (SN)	BROKEN	80.82	40.41
8	POP-RIVET (SN)	NECESSARY	4.24	2.12
1	WHEELHOUSE PROTECTOR RHS REAR FENDER LINER (SN)	CRUSHED	249.07	124.54
1	SIDE MEMBER TRIM RHR FENDER LINER LOWER TRIM (SN)	CRUSHED	39.81	19.91
1	ALLOY WHEEL DIAMEND SILVE (SN)	NOT NECESSARY	999.26	-
1	RUBBER VALVE (SN)	NOT NECESSARY	3.60	-
1	RADIATOR MIT MONTAGE TELL RHR WHEEL BEARING (SN)	JAMMED	596.57	298.29
1	STAB AXLE (SN)	NECESSARY	296.19	148.10
4	BOLT HEX.HD (SN)	NECESSARY	18.20	9.10
1	REAR AXLE BEAM (SN)	BENT	2,602.74	1,301.37
2	HEXAGON FIANGE SCREW (SN)	NECESSARY	23.74	11.87
8	BOLT HEX.HD (SN)	NECESSARY	48.00	24.00
2	BOLT HEX.HD.WITH SHOULD (SN)	NECESSARY	16.30	8.15
1	DEGREASER CLEANER 500ML (SN)	NECESSARY	18.80	9.40
1	PIRELLL CINTUP7 205/55R16 (SN)	TORN	680.00	544.00

Report Ref No. CC4/LPC21009383/Egs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RHR DOOR TRIM (SN)(ADDITIONAL)	BROKEN	48.74	48.74
			31,519.30	9,328.51
	LABOUR			
	TOWING ASSISTANCE -AWP .		195.00	195.00
	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR .		280.00	280.00
	B&P DIAGNOSIS AND PREGRAMMING .		480.00	480.00
	R&R ROOFLINING.		2,520.00	630.00
	R&R FRT SEAT BELT & AIRBAG CONTROL UNIT.		1,680.00	420.00
	R&R REAR AXLE BEAM .		3,360.00	630.00
	R&R WHEEL BEARING .	NOT NECESSARY	840.00	-
	B&P WHEEL ALIGNMENT .		360.00	180.00
	R&R TYRE & BALANCE.		50.00	50.00
	LABOUR.		10,080.00	4,200.00
	SPRAY PAINT.		6,400.00	2,000.00
	R&R FRT SEAT & CARPPET.		1,680.00	420.00
	R&R REAR LUGGAGE TRIM .		840.00	210.00
	R&R REAR SEAT.		840.00	210.00
	TRANSFER DOOR MECHANISM .		1,680.00	420.00
	VEHICLE ON BENCH -CELATTE.		1,500.00	750.00
	R&R FRT SEAT AIRBAG.		360.00	180.00
	R&R RHS FRT DOOR BOARD LEATHER.		360.00	180.00
	R&R RHS REAR DOOR BOARD LEATHER.	NOT NECESSARY	360.00	-
	REPAIR AND SPRAY PAINT RIM .(ADDITIONAL)		400.00	200.00
			34,265.00	11,635.00
GRAND TOTAL			65,784.30	20,963.51
RECOMMENDED COST OF REPAIRS				20,963.51

Report Ref No. CC4/LPC21009383/Egs3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLB 1020H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLB 1020H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLB 1020H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

