



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0725/2021/TF
DATE : 4-Sep-21
WIP : 42722

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

9 days exclude 1 Sunday

Johnny Boo 13 Oct 21

OWNER'S NAME : MS LIM CHIEW LAN
ADDRESS : BLK 414 TAMPINES ST 41
#10-309
SINGAPORE 520414
TELEPHONE : HP +65 97524232
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070126274-01
VEHICLE NO : **SMU 8013 X**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI S TRONIC
MODEL YEAR : 8/28/2020
ENGINE NO : CHZ C34974
CHASSIS NO : WAUZZZ8V9LA007302
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Sep-21
PLACE OF ACCIDENT : BLK 263 TAMPINES ST 21

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 8013 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	\$ 360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	\$ 500.00
3	TO RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,400.00	\$ 1,400.00
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS.	S/N \$ 560.00	\$ 280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	\$ 3,250.00
6	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDERS, HINGES, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS.	\$ 6,800.00	\$ 2,850.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		: \$ 15,804.00	\$ 9,024.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
1	FRONT BUMPER	1	\$	1,987.00	\$ 1,589.60
2	FRONT BUMPER FIXING PARTS	1	\$	187.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$	78.00	
4	FRONT BUMPER LOWER GRILLE	1	\$	160.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$	536.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$	594.00	\$ 474.40
7	FRONT BUMPER COVER TRIM - LH / RH	2	\$	326.00	
8	FRONT BUMPER ADAPTERE - LH / RH	2	\$	76.00	
9	RADIATOR GRILLE	1	\$	1,406.00	\$ 1,124.80
10	RADIATOR GRILLE CLOSING ELEMENT	1	\$	191.00	\$ 152.40
11	FRONT BUMPER AIR GRILLE - LH / RH	2	\$	376.00	
12	FRONT BUMPER REINFORCEMENT FORM	1	\$	189.00	\$ 151.20
13	FRONT BUMPER REINFORCEMENT	1	\$	795.00	\$ 636.00
14	FRONT BUMPER REINFORCEMENT COVER	1	\$	122.00	\$ 97.20
15	A/C STICKER	1	\$	8.00	\$ 5.68
16	CAUTION STICKER	1	\$	14.00	\$ 10.88
17	HORN - LH / RH	2	\$	400.00	
18	FRONT FENDER - LH / RH	2	\$	1,702.00	\$ 1,360.80
19	RIVET	10	\$	33.00	\$ 26.40
20	FRONT FENDER ATTACHMENT PARTS	1	\$	72.00	
SUB TOTAL SPARE PARTS		:	\$	9,252.00	\$ 5,629.36

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			S/NETT		REMARKS
		<i>c/f</i>		\$	5,629.36
21	FRONT FENDER TOP BRACKET - FRONT LH / RH	2	\$	78.00	\$ 61.44
22	FRONT FENDER TOP BRACKET - REAR LH / RH	2	\$	56.00	
23	FRONT FENDER BRACE - LH / RH	2	\$	192.00	\$ 152.96
24	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	338.00	
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	89.00	
26	FRONT BONNET	1	\$	3,134.00	\$ 2,507.20
27	FRONT BONNET ATTACHMENT PARTS	1	\$	165.00	
28	FRONT BONNET HINGE - LH / RH	2	\$	124.00	\$ 97.76
29	FRONT BONNET CATCH	1	\$	90.00	\$ 71.28
30	FRONT BONNET STRIKER - LH / RH	2	\$	220.00	\$ 87.60
31	FRONT BONNET EDGE PROTECTION	1	\$	28.00	\$ 22.00
32	FRONT BONNET LOWER CATCH	1	\$	63.00	\$ 50.32
33	FRONT BONNET LOCK	2	\$	427.00	\$ 170.80
34	FRONT BONNET BOWDEN CABLE - CENTRE	1	\$	58.00	
35	FRONT BONNET BOWDEN CABLE COVER	1	\$	10.00	
36	FRONT BONNET LOCK CABLE	1	\$	74.00	
37	FRONT BONNET SOUND ABSORBER	1	\$	219.00	
38	FRONT PLENUM CHAMBER COVER	1	\$	179.00	
39	HEADLIGHT - LH / RH	2	\$	10,910.00	\$ 8,728.00
40	HEADLIGHT POWER MODELE - LH	1	\$	758.00	
SUB TOTAL SPARE PARTS		:	\$	17,212.00	\$ 17,578.72

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 17,578.72
41	HEADLIGHT CONTROL UNIT - LIGHT CONTROL	1	\$ 557.00	
42	HEADLIGHT HEAT SINK - LH	1	\$ 733.00	
43	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 284.00	
44	HEADLIGHT LIFT CYLINDER HOSE	1	\$ 68.00	
45	FRONT LOCK CARRIER	1	\$ 727.00	\$ 581.60
46	CONDENSER	1	\$ 529.00	
47	TEMPRETURE SENSOR BRACKET	1	\$ 19.00	
48	RADIATOR	1	\$ 951.00	
49	ADDITIONAL RADIATOR	1	\$ 856.00	
50	RADIATOR FAN	1	\$ 1,265.00	
51	COOLANT	6	\$ 266.00	\$ 212.64
52	RADIATOR AIR GUIDE - LH / RH / UPPER CENTRE	3	\$ 62.00	\$ 48.32
53	RADIATOR AIR GUIDE SEAL - RIGHT OUTER	1	\$ 8.00	
54	INTAKE AIR DUCT TOP COVER	1	\$ 29.00	
55	INTAKE AIR DUCT	1	\$ 55.60	\$ 44.48
56	INTAKE AIR DUCT AIR GUIDE	1	\$ 20.00	
57	WATER DRAINAGE HOSE	1	\$ 33.00	
58	INTAKE AIR DUCT AIR GUIDE HOSE	1	\$ 66.00	
59	RADIATOR BRACKET	2	\$ 82.00	
60	RADIATOR BUSH	2	\$ 19.00	
SUB TOTAL SPARE PARTS		:	\$ 6,629.60	\$ 18,465.76

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 18,465.76
61	WATER DEFLECTOR STRIP - LH / RH	2	\$ 186.00	
62	FRONT WINDOW SLOT SEAL CHROME TRIM - LH / RH	2	\$ 618.00	
63	FRONT NO. PLATE	S/N	\$ 60.00	\$ 60.00
63	ADDED PARTS - SEE ATTACHED		\$ 202.00	\$ 161.60
64	SUNDRIES		\$ 400.00	\$ 57.60
TOTAL SPARE PARTS		:	\$ 34,559.60	\$ 18,744.96
TOTAL LABOUR CHARGES		:	\$ 15,804.00	\$ 9,024.00
GRAND TOTAL		:	\$ 50,363.60	\$ 27,768.96

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-08/10/21



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0725/2021/TF 10-Sep-21 CHANG 1 of 1 SMU 8013 X AUDI A3 SEDAN 1.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	FAN RING	\$ 202.00	\$	161.60
GRAND TOTAL		\$ 202.00	\$	161.60

For Premium Automobiles Pte Ltd

 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT