

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0725/2021/TF
DATE : 4-Sep-21
WIP : 42722

Denise
\$ 27768.56.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 6/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LIM CHIEW LAN
ADDRESS : BLK 414 TAMPINES ST 41
#10-309
SINGAPORE 520414
TELEPHONE : HP +65 97524232
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070126274-01
VEHICLE NO : **SMU 8013 X**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI S TRONIC
MODEL YEAR : 28/8/2020
ENGINE NO : CHZ C34974
CHASSIS NO : WAUZZZ8V9LA007302
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Sep-21
PLACE OF ACCIDENT : BLK 263 TAMPINES ST 21



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 8013 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00 500	✓
3	TO RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,400.00	✓✓
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS.	S/N \$ 560.00 280	✓
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00 2850	3250 ✓
6	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDERS, HINGES, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS.	\$ 6,800.00 2850	5 x 550 = 2750 Hinge = 50 x 2 = 100 ✓ 2850
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ ✓ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 15,804.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	S/NETT	REMARKS
					1589.60
1	FRONT BUMPER <i>Distorted</i>	1	S	1,987.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	S	187.00	+
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	S	78.00	+
4	FRONT BUMPER LOWER GRILLE <i>new</i>	1	S	160.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	S	536.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	S	594.00	+
7	FRONT BUMPER COVER TRIM - LH / RH <i>new</i>	2	S	326.00	+
8	FRONT BUMPER ADAPTERE - LH / RH <i>new</i>	2	S	76.00	+
9	RADIATOR GRILLE <i>Smashed</i>	1	S	1,406.00	+
10	RADIATOR GRILLE CLOSING ELEMENT <i>smashed</i>	1	S	191.00	+
11	FRONT BUMPER AIR GRILLE - LH / RH <i>new</i>	2	S	376.00	+
12	FRONT BUMPER REINFORCEMENT FORM <i>cracked bent</i>	1	S	189.00	+
13	FRONT BUMPER REINFORCEMENT	1	S	795.00	+
14	FRONT BUMPER REINFORCEMENT COVER <i>cracked</i>	1	S	122.00	+
15	A/C STICKER	1	S	8.00	+
16	CAUTION STICKER <i>new</i>	1	S	14.00	+
17	HORN - LH / RH <i>new</i>	2	S	400.00	+
18	FRONT FENDER - LH / RH <i>Buckled</i>	2	S	1,702.00	+
19	RIVET <i>new</i>	10	S	33.00	+
20	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	S	72.00	+
SUB TOTAL SPARE PARTS			:	\$ 9,252.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL 6366 2323 FAX 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
21	FRONT FENDER TOP BRACKET - FRONT LH / RH <i>Bent</i>	2	\$ 78.00	✓	61.44	
22	FRONT FENDER TOP BRACKET - REAR LH / RH <i>new</i>	2	\$ 56.00	+		
23	FRONT FENDER BRACE - LH / RH <i>bent</i>	2	\$ 192.00	.	152.96	
24	FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>	2	\$ 338.00	x		
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 89.00	+	2507.2	
26	FRONT BONNET <i>new</i>	1	\$ 3,134.00	✓		
27	FRONT BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 165.00	+	97.76	
28	FRONT BONNET HINGE - LH / RH <i>Bent</i>	2	\$ 124.00		71.28	
29	FRONT BONNET CATCH <i>Bent</i>	1	\$ 90.00		87.60	
30	FRONT BONNET STRIKER - LH / RH <i>LH bent</i>	2	\$ 220.00		22	
31	FRONT BONNET EDGE PROTECTION <i>new</i>	1	\$ 28.00		50.32	
32	FRONT BONNET LOWER CATCH <i>Bent</i>	1	\$ 63.00		170.8	
33	FRONT BONNET LOCK ?	2	\$ 427.00			
34	FRONT BONNET BOWDEN CABLE - CENTRE <i>new</i>	1	\$ 58.00	x		
35	FRONT BONNET BOWDEN CABLE COVER <i>new</i>	1	\$ 10.00	x		
36	FRONT BONNET LOCK CABLE <i>new</i>	1	\$ 74.00	+		
37	FRONT BONNET SOUND ABSORBER <i>new</i>	1	\$ 219.00	x		
38	FRONT PLENUM CHAMBER COVER <i>new</i>	1	\$ 179.00	+	8728	
39	HEADLIGHT - LH / RH <i>new</i>	2	\$ 10,910.00	✓		
40	HEADLIGHT POWER MODELE - LH <i>new</i>	1	\$ 758.00	x		
SUB TOTAL SPARE PARTS		:	\$ 17,212.00			

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT CONTROL UNIT - LIGHT CONTROL <i>not in</i>	1	S 557.00	+
42	HEADLIGHT HEAT SINK - LH <i>not in</i>	1	S 733.00	+
43	HEADLIGHT LIFT CYLINDER - LH / RH <i>not in</i>	2	S 284.00	+
44	HEADLIGHT LIFT CYLINDER HOSE <i>not in</i>	1	S 68.00	+
45	FRONT LOCK CARRIER <i>could</i>	1	S 727.00	+
46	CONDENSER <i>Not nec</i>	1	S 529.00	+
47	TEMPRETURE SENSOR BRACKET <i>Not in</i>	1	S 19.00	+
48	RADIATOR <i>Not nec</i>	1	S 951.00	+
49	ADDITIONAL RADIATOR <i>Not nec</i>	1	S 856.00	+
50	RADIATOR FAN <i>Not nec</i>	1	S 1,265.00	+
51	COOLANT <i>Not</i>	6	S 266.00	+
52	RADIATOR AIR GUIDE - LH / RH / UPPER CENTRE <i>to in</i>	3	S 62.00	+
53	RADIATOR AIR GUIDE SEAL - RIGHT OUTER <i>Not nec</i>	1	S 8.00	+
54	INTAKE AIR DUCT TOP COVER <i>not in</i>	1	S 29.00	+
55	INTAKE AIR DUCT <i>cracked</i>	1	TBC 55.6	+
56	INTAKE AIR DUCT AIR GUIDE <i>Not nec</i>	1	S 20.00	+
57	WATER DRAINAGE HOSE <i>not in</i>	1	S 33.00	+
58	INTAKE AIR DUCT AIR GUIDE HOSE <i>Not in</i>	1	S 66.00	+
59	RADIATOR BRACKET <i>Not nec</i>	2	S 82.00	+
60	RADIATOR BUSH <i>Not nec</i>	2	S 19.00	+
SUB TOTAL SPARE PARTS		:	<u>S 6,574.00</u>	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	WATER DEFLECTOR STRIP - LH / RH <i>not nec</i>	2	\$ 186.00	f
62	FRONT WINDOW SLOT SEAL CHROME TRIM - LH / RH <i>not nec</i>	2	\$ 618.00	f
63	FRONT NO. PLATE <i>Bent.</i>	S/N	\$ 60.00	✓
64	SUNDRIES <i>Xlec</i>		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 34,302.00	
TOTAL LABOUR CHARGES		:	\$ 15,804.00	
GRAND TOTAL		:	\$ 50,106.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

◆ PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King
SURVEYED DATE : 09/09/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 09 Days. *[Signature]*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT