

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

Denise

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
 Attn: Mr. Adrian Ling - Motor Claims Dept
 Tel: 6841 0055 / Fax: 6256 4315

Estimate No. PA/OD/0725/2021/TF
Date 10-Sep-21
Service Advisor CHANG
Pages 1 of 1
Regn No SMU 8013 X
Model No AUDI A3 SEDAN 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FAN RING <i>cracked</i>	161.60	\$ 202.00 ✓
GRAND TOTAL		\$ 202.00	

For Premium Automobiles Pte Ltd

Adrian Ling
10/09/21



Authorised Signatur :

Car-in

9/9/21

wp= 42722

PREMIUM AUTOMOBILES

kiam/ choy



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIG- Adrian

- 9 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

S/N	PARTS DESCRIPTION	QTY	S/NETT	DAMAGED PARTS & PRICES	REMARKS
1	FRONT BUMPER Distorted	1	\$	1,987.00	✓
2	FRONT BUMPER FIXING PARTS new	1	\$	187.00	+
3	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$	78.00	?
4	FRONT BUMPER LOWER GRILLE new	1	\$	160.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE new	1	\$	536.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH new	2	\$	594.00	4 ✓
7	FRONT BUMPER COVER TRIM - LH / RH new	2	\$	326.00	+
8	FRONT BUMPER ADAPTERE - LH / RH	2	\$	76.00	+
9	RADIATOR GRILLE Smashed	1	\$	1,406.00	-
10	RADIATOR GRILLE CLOSING ELEMENT Smashed	1	\$	191.00	✓
11	FRONT BUMPER AIR GRILLE - LH / RH new	2	\$	376.00	+
12	FRONT BUMPER REINFORCEMENT FORM checked	1	\$	189.00	✓
13	FRONT BUMPER REINFORCEMENT Bent	1	\$	795.00	✓
14	FRONT BUMPER REINFORCEMENT COVER Cracked	1	\$	122.00	✓
15	A/C STICKER	1	\$	8.00	✓
16	CAUTION STICKER new	1	\$	14.00	✓
17	HORN - LH / RH new	2	\$	400.00	+
18	FRONT FENDER - LH / RH Buckled	2	\$	1,702.00	✓
19	RIVET new	10	\$	33.00	✓
20	FRONT FENDER ATTACHMENT PARTS new	1	\$	72.00	+
SUB TOTAL SPARE PARTS			:	\$ 9,252.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian
Resurveyed 10/09/21
S/S.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER TOP BRACKET - FRONT LH / RH <i>Best</i>	2 S	78.00	✓
22	FRONT FENDER TOP BRACKET - REAR LH / RH <i>Neu</i>	2 S	56.00	+
23	FRONT FENDER BRACE - LH / RH <i>Best</i>	2 S	192.00	✓
24	FRONT WHEEL HOUSING LINER - LH / RH <i>Neu</i>	2 S	338.00	x
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Neu</i>	1 S	89.00	+
26	FRONT BONNET <i>Brucoid</i>	1 S	3,134.00	✓
27	FRONT BONNET ATTACHMENT PARTS <i>Neu</i>	1 S	165.00	+
28	FRONT BONNET HINGE - LH / RH <i>Best</i>	2 S	124.00	✓
29	FRONT BONNET CATCH <i>Best</i>	1 S	90.00	✓
30	FRONT BONNET STRIKER - LH / RH <i>LH Best</i>	2 S	220.00 110.	
31	FRONT BONNET EDGE PROTECTION <i>Neu</i>	1 S	28.00	✓
32	FRONT BONNET LOWER CATCH <i>Best</i>	1 S	63.00	✓
33	FRONT BONNET LOCK ? - LH <i>Best</i>	2 S	427.00 213.50.	
34	FRONT BONNET BOWDEN CABLE - CENTRE ?	1 S	58.00	?
35	FRONT BONNET BOWDEN CABLE COVER ?	1 S	10.00	?
36	FRONT BONNET LOCK CABLE <i>Neu</i>	1 S	74.00	+
37	FRONT BONNET SOUND ABSORBER <i>Neu</i>	1 S	219.00	x
38	FRONT PLENUM CHAMBER COVER <i>Neu</i>	1 S	179.00	+
39	HEADLIGHT - LH / RH <i>Brucoid</i>	2 S	10,910.00	✓
40	HEADLIGHT POWER MODELE - LH <i>Neu</i>	1 S	758.00	x
SUB TOTAL SPARE PARTS			\$ 17,212.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	HEADLIGHT CONTROL UNIT - LIGHT CONTROL <i>ok</i>	1	S	557.00	<i>+</i>
42	HEADLIGHT HEAT SINK - LH <i>ok</i>	1	S	733.00	<i>+</i>
43	HEADLIGHT LIFT CYLINDER - LH / RH <i>ok</i>	2	S	284.00	<i>+</i>
44	HEADLIGHT LIFT CYLINDER HOSE <i>ok</i>	1	S	68.00	<i>+</i>
45	FRONT LOCK CARRIER <i>ok</i>	1	S	727.00	<i>+</i>
46	CONDENSER ?	1	S	529.00	<i>+</i>
47	TEMPRETURE SENSOR BRACKET ?	1	S	19.00	<i>+</i>
48	RADIATOR ?	1	S	951.00	<i>+</i>
49	ADDITIONAL RADIATOR ?	1	S	856.00	<i>+</i>
50	RADIATOR FAN ?	1	S	1,265.00	<i>+</i>
51	COOLANT <i>ok</i>	6	S	266.00	<i>+</i>
52	RADIATOR AIR GUIDE - LH / RH / UPPER CENTRE <i>ok</i>	3	S	62.00	<i>+</i>
53	RADIATOR AIR GUIDE SEAL - RIGHT OUTER ?	1	S	8.00	<i>+</i>
54	INTAKE AIR DUCT TOP COVER ?	1	S	29.00	<i>+</i>
55	INTAKE AIR DUCT <i>ok</i>	1		TBC	<i>56.00</i>
56	INTAKE AIR DUCT AIR GUIDE ?	1	S	20.00	<i>+</i>
57	WATER DRAINAGE HOSE <i>ok</i>	1	S	33.00	<i>+</i>
58	INTAKE AIR DUCT AIR GUIDE HOSE ?	1	S	66.00	<i>+</i>
59	RADIATOR BRACKET ?	2	S	82.00	<i>+</i>
60	RADIATOR BUSH ?	2	S	19.00	<i>+</i>
SUB TOTAL SPARE PARTS			:	\$ 6,574.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8013 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	WATER DEFLECTOR STRIP - LH / RH <i>need rec</i>	2	\$	186.00	<i>+</i>
62	FRONT WINDOW SLOT SEAL CHROME TRIM - LH / RH <i>not m</i>	2	\$	618.00	<i>+</i>
63	FRONT NO. PLATE <i>Bent.</i>	S/N	\$	60.00	<i>✓</i>
64	SUNDRIES ?		\$	400.00	<i>?</i>
TOTAL SPARE PARTS		:	\$	34,302.00	
TOTAL LABOUR CHARGES		:	\$	15,804.00	
GRAND TOTAL		:	\$	<u>50,106.00</u>	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.