

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21009389/DUF3E2

Date: 24/11/2021

REFERENCE

| | | | | | |
|------------------------------|--------------------------------------|-----------------------------|------------|-----------|--------|
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. | Policy No: | 1001428155 | | |
| Claimant Vehicle No : | FBK6971B | Insured Vehicle No : | SKC238K | | |
| Date of Loss: | 24/07/2021 | Nature of Claim: | TP | Claim No: | 260468 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | FBK6971B | Engine No: | G3E3E0011643 |
| Make & Model: | YAMAHA FZN150, 149cc | Chassis No: | ME1RG1618F2001680 |
| Reg. Date: | 22/12/2015 (Man. Year: 2015) | Odometer: | 0 km |
| Colour: | Red | | |
| Engine Capacity: | 149 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 100/80 R17 | Rear Tyre Size: | 140/70 R17 |
| Front Left Side: | Michelin 2 mm | Rear Left Side: | Michelin 2 mm |
| Front Right Side: | 0 mm | Rear Right Side: | 0 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 3,010.50 | 1,413.00 | 1,597.50 | 53.06 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 510.00 | 230.00 | 280.00 | 54.90 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 3,520.50 | 1,643.00 | 1,877.50 | 53.33 |
| Approved Total (Overridden) (S\$) | | 1,000.00 | | |
| Nett Amount (S\$) | 3,520.50 | 1,000.00 | 2,520.50 | 71.59 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---------------------------------------|
| Date of Assignment: | 07/09/2021 | Sg 98 Motor Pte Ltd (HQ) |
| Date Inspected: | 08/09/2021 Inspected At: | BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 |
| | | #01-21 |
| | | Singapore 569622 |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: BRYAN TANI

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|---|
| Reference | | |
| Part Source: | (Last Synchronised: 24 Nov 2021) | |
| Parts: | N/A | YAMAHA FZN150 149cc (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for FBK6971B) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------|-----------------------------|------------|------------|
| 1 | 1 | | *SET FORK TUBE | Distorted | 480.00 FL | *480.00 FL |
| 2 | 1 | | *HANDLE BAR | Distorted | 150.00 FL | *150.00 FL |
| 3 | 1 | | *FRONT MUDGUARD | Serviceable | 230.00 FL | *- FL |
| 4 | 1 | | *MIRROR RH | Cut | 85.00 FL | *85.00 FL |
| 5 | 1 | | *FRONT RH SHROUD | Repair | 135.00 FL | *- FL |
| 6 | 1 | | *TANK COVER RH | Cut | 220.00 FL | *220.00 FL |
| 7 | 1 | | *HANDLE GRIP | Cut | 135.00 FL | *135.00 FL |
| 8 | 1 | | *BAR END | O/S Cut / N/S Not Necessary | 190.00 FL | *95.00 FL |
| 9 | 1 | | *BRAKE LEVER | Cut | 80.00 FL | *80.00 FL |
| 10 | 1 | | *FRONT RH SIGNAL | Cut | 75.00 FL | *75.00 FL |
| 11 | 1 | | *FRONT LH SIGNAL | Not Necessary | 85.00 FL | *- FL |
| 12 | 1 | | *HEAD LAMP SIDE GUARD RH | Serviceable | 280.00 FL | *- FL |
| 13 | 1 | | *REAR BOX (KAPPA) | Cut | 380.00 FS | *150.00 FS |
| 14 | 1 | | *SET FRONT & NUMBER PLATE | Cut | 30.00 FS | *15.00 FS |
| 15 | 1 | | *SET BODY DECAL STICKER | Necessary | 120.00 FS | *60.00 FS |
| 16 | 1 | | *METER ASSY | Serviceable | 550.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|----------|----------|
| Sub Total (S\$) | 3,225.00 | 1,545.00 |
| - List Item Discount on L Items 10.00/10.00% (S\$) | 214.50 | 132.00 |
| Total Parts (S\$) | 3,010.50 | 1,413.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | TOWING FEE | New | 50.00 | 0.00 |
| 2 | REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC | New | 250.00 | 150.00 |
| 3 | REMOVE & REPLACE FORK TUBE & TOP UP FORK OIL | New | 120.00 | 80.00 |
| 4 | REPRESS FORK RIM | New | 90.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 510.00 | 230.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >