

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 18 Nov 2021

Preliminary Advice

Insured Vehicle No	: SKC238K	Accident Date	: 24/07/2021
TP Vehicle No	: FBK6971B	Assignment Date	: 07/09/2021
Make	: YAMAHA FZN150	Est. Duration of Repair	: 4
Date of Inspection	: 08/09/2021		
Inspection At	: SG 98 MOTOR PTE LTD (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,520.50
Revised Amount	:S\$	1,643.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,643.00
 Lump Sum Repair	 :S\$	 1,300.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	4,000.00
COE / PARF Rebate	:S\$	2,661.00
Salvage Value	:S\$	
Margin for Repair	:S\$	1,339.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.