

Steve CS/40121229396/EV3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/INS/TPR/OD-RES/EVA/INV/MV
To inspect Vehicle Not _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____
(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.
Est. or Market Value: _____
IDAC Accident Report _____ Consistent? Yes or No
SIA / PR Seen _____ Consistent? Yes or No
Est. Repairs: _____ days Res.: Yes or No
Cum Sum: _____ % 3 Val.: Yes or No
QA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: GRL 1879M Yr Regn: 29/3/21
Types M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Hiace Ch: 2982
Colour: Silver A/O: Insured / Std / NI / N
Sp. Reading: 11/A T/Radio: Insured / Std / NI / N
Eng/No: _____
C/No: TTFHT 920:2002516/15
Gen. Cond: Good / Fair / Poor / Bupl
Steering: In order / Jammed / Locked / Burnt or
Brakes: In order / Jammed / Locked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195R15C R: _____
ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bel. 4 mm R/Bel. 4 mm
L/Bel. 4 mm L/Bel. 4 mm
D.O.A. 6/9/21 D.O.I. 8/9/21
Survey held at Borneo Motors
Des. of Damages: Front / Rear / O/S / N/S / U/C / Roof/Top or
Interior
The U/C / CHASSIS frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV- 84K</u>
	<u>PV- 26,398</u>
	<u>NK- 5.7, 602</u>

Time/Time, File, Retn ltr. ☐ Prel. Report
☐ Final Report
Time/Time, File Retn ltr.

Days Of Repair: _____
Resurvey No. of Trips: _____

Add Fee: ☐ Site Insp (\$ _____)
☐ Interview (\$ _____)
☐ Tech. Inve (\$ _____)
☐ Weekend (\$ _____)

Survey Fee:
Transportation: _____
Provision: _____
Others: _____
TOTAL: _____

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462. Tel no : 6631 1188

**TOYOTA**

Steve CLKK)
 8/9/21, 12:00pm

00-11-1 AL
 EXCII-1-7

P/P

My BL by, 14 days

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUOI1	M/S Sim Solutions Pte Ltd 126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355 Mobile: 84372553
	Document No. 0	
	Document Date 06/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:20135652 ACC DATE:05.09.2021 TOW IN:06.09.2021 EXCESS: DATE-IN:06.09.2021 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT				200 500.00
3	S	BP-SUBLET REPLACE AND REFOCUS HEADLAMP				122.40
4	S	BP-SUBLET R/I AC CONDENSOR, PIPING AND REGAS				360.00
5	S	BP-SUBLET REPLACE DASHBOARD ASSY TO FAC REPAIR.				1440.00
6	S	BP-SUBLET REPLACE FRONT WINDSCREEN GLASS				462.00
7	Z	BP-BKT SUPPLY IU BRACKET				26.00
8	S	BP-SUBLET REPLACE AIR BAG SENSOR, CONTROL AND SAFE TY BELT AS				1440.00
9	S	BP-SUBLET REPLAC FRONT BOTH SEATS..				1440.00
10	S	BP-SUBLET R/I ROOF LINING ASSY TEO FAC REPAIR.				1440.00
11	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				360 720.00
12	S	BP-SUBLET REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR				360.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUO11	M/S Sim Solutions Pte Ltd 126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355 Mobile: 84372553
	Document No. 0	
	Document Date 06/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST				122.40
14	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00
15	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	6 X 710			4320 7200.00
16	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS	6 X 590			3540 5900.00
17	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00
18	L	BP-LPO SUPPLY COMPANY DOOR STICKER- 2PC				50 100.00
19	S	BP-SUBLET REMOVE INTERIOR SHATTED GLASS				180.00
20	Z	TW TOWING CHARGES				120.00
21	L	BP-LPO SUPPLY CARGE BARRIER				880.00
22	1	T52119-26651 COVER, FR BUMPER	1.00	546.30		546.30
23	2	T53112-26060 GRILLE, RADIATOR,	1.00	57.00		57.00
24	3	T53113-26060 GRILLE, RADIATOR,	1.00	57.00		57.00
25	4	S52161-0K040 PIECE,RR BUMPER	10.00	4.10		41.00
26	5	T53112-26070 GRILLE, RADIATOR,	1.00	179.70		179.70
27	6	T52127-26200 B0 COVER, FR BUMPER	1.00	13.80		13.80
28	7	T52127-26200 B0 COVER, FR BUMPER	1.00	13.80		13.80
29	8	T52127-26200 B0 COVER, FR BUMPER	1.00	13.80		13.80
30	9	T52115-26210 SUPPORT, FR BUMPER	1.00	144.60		144.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUO11	M/S Sim Solutions Pte Ltd
	Document No. 0	126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355
	Document Date 06/09/2021	Mobile: 84372553

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
31	0	T52116-26210 SUPPORT, FR BUMPER	1.00	144.60		144.60
32	1	T57053-26030 REINFORCE SUB-ASSY,	1.00	154.80		154.80
33	2	T52131-26021 REINFORCEMENT, FR	1.00	361.30		361.30
34	3	T58127-26050 R/F MEMBER CROSS REINFOR	1.00	55.10		55.10
35	4	T53036-26020 L/F MEMBER CROSS REINFOR	1.00	57.30		57.30
36	5	T53111-26500 GRILLE, RADIATOR,	1.00	223.80		223.80
37	6	T53111-26510 GRILLE, RADIATOR,	1.00	386.90		386.90
38	7	T53112-26090 GRILLE, RADIATOR,	1.00	573.90		573.90
39	8	T53301-26080 FRONT BONNET ASSY,	1.00	1030.90		1030.90
40	9	T53801-26011 R/FRONT FENDER PANEL.	1.00	271.10		271.10
41	0	T53802-26021 L/FRONT FENDER PANEL.	1.00	271.10		271.10
42	1	T53803-26011 R/FRT SIDE BRACKET,	1.00	44.50		44.50
43	2	T53410-26041 HINGE ASSY, HOOD, RH	1.00	59.30		59.30
44	3	T53420-26041 HINGE ASSY, HOOD, LH	1.00	59.30		59.30
45	4	T53510-26060 FRONT BONNET LOCK,	1.00	95.00		95.00
46	5	T53201-26082 SUPPORT SUB-ASSY,	1.00	381.00		381.00
47	6	T53209-26130 BRACE SUB-ASSY, HOOD	1.00	36.20		36.20
48	7	T57109-26021 REINFORCEMENT	1.00	457.40		457.40
49	8	T57104-26191 F/LOWER CROSS-MEMBER,	1.00	404.90		404.90
50	9	T55300-26120 B0 PANEL ASSY, (Dashboard)	1.00	960.50		960.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

**Borneo Motors****TOYOTA**

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUOI1	M/S Sim Solutions Pte Ltd
	Document No. 0	126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355
	Document Date 06/09/2021	Mobile: 84372553

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
51	0	T55406-26120 B0 PANEL SUB-ASSY,	1.00	669.40		669.40
52	1	T55330-26311 REINFORCEMENT ASSY,	1.00	767.00		767.00
53	2	T61183-26020 BRACKET, INSTRUMENT	1.00	22.20		22.20
54	3	T61184-26020 BRACKET, INSTRUMENT	1.00	22.20		22.20
55	4	T55309-26030 BRACE SUB-ASSY,	1.00	46.40		46.40
56	5	T90467-07215 CLIP	10.00	2.60		26.00
57	6	T55317-26071 B0 PATCH, INSTRUMENT	1.00	6.70		6.70
58	7	T55539-26140 C0 COVER, SPARE SWITCH	1.00	11.50		11.50
59	8	T55405-26220 B1 INSTRUMENT PANEL CLUSTER	1.00	652.30		652.30
60	9	T55410-26140 B1 PANEL ASSY,	1.00	209.80		209.80
61	0	T55432-26170 B0 PANEL, INSTRUMENT	1.00	367.30		367.30
62	1	T55404-26430 B0 PANEL SUB-ASSY,	1.00	316.40		316.40
63	2	T55550-26010 B0 FRT GLOVE COMPARTMENT	1.00	352.50		352.50
64	3	T55434-26150 B0 PANEL, INSTRUMENT	1.00	199.50		199.50
65	4	T58941-26080 B0 COVER, PARKING BRAKE	1.00	94.00		94.00
66	5	T55641-26060 B0 COVER, INSTRUMENT	1.00	250.20		250.20
67	6	T55539-58130 C0 COVER, SPARE SWITCH	1.00	13.30		13.30
68	7	T55539-26140 C0 COVER, SPARE SWITCH	1.00	11.50		11.50
69	8	T55539-52040 B0 COVER, SPARE SWITCH	1.00	12.20		12.20
70	9	T55521-44020 COVER, STEREO	2.00	59.20		118.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details			
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000019 / ICUOI1	M/S Sim Solutions Pte Ltd 126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355 Mobile: 84372553			
		Document No. 0				
		Document Date 06/09/2021				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
71	0	T55448-26010 CUSHION, INSTRUMENT	1.00	17.50		17.50
72	1	T55474-26030 B0 GARNISH, INSTR CSTR	1.00	95.50		95.50
73	2	T55475-26030 B0 GARNISH, INSTR CSTR	1.00	95.50		95.50
74	3	T55708-26090 F/TOP COWL VENTILATOR, CRU	1.00	587.60		587.60
75	4	T53866-26011 R/FRT FENDER SEAL CRU	1.00	18.80		18.80
76	5	T55877-26030 R/FRT VENT COWL COVER MIS	1.00	26.40		26.40
77	6	T55878-26030 L/FRT COWL VENT COVER	1.00	26.40		26.40
78	7	T53867-26011 L/FRT FENDER SEAL X	1.00	18.80		18.80
79	8	T55700-26440 PANEL ASSY,COWL FR	1.00	752.40		752.40
80	9	T55757-26040 PLATE,HEATER AIR	1.00	101.00		101.00
81	0	T61101-26040 PANEL SUB ASSY,COWL	1.00	155.90		155.90
82	1	T61123-26020 PANEL,COWL SIDE	1.00	184.60		184.60
83	2	T61131-26091 PILLAR, FR BODY,	1.00	438.30		438.30
84	3	T55705-26080 PANEL SUB-ASSY,COWL	1.00	111.80		111.80
85	4	T53271-26021 BRACKET HEADLAMP	1.00	59.30		59.30
86	5	T61311-26050 PILLAR, CTR BODY	1.00	511.20		511.20
87	6	T61215-26040 RAIL, ROOF SIDE,	1.00	128.40		128.40
88	7	T61037-26030 REINFORCEMENT	1.00	547.00		547.00
89	8	T61343-26400 PILLAR, CTR BODY,	1.00	270.50		270.50
90	9	T61108-26010 REINFOCE SUB ASSY	1.00	228.70		228.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUOI1	M/S Sim Solutions Pte Ltd
	Document No. 0	126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355
	Document Date 06/09/2021	Mobile: 84372553

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
91	0	T53827-26010 R/F FENDER PROTECTOR, 1	1.00	49.90		49.90
92	1	T53827-26010 L/F FENDER PROTECTOR, X	1.00	49.90		49.90
93	2	T62210-26041 B0 GARNISH ASSY, FR ?	1.00	185.20		185.20
94	3	T62313-26010 C0 TRIM, FR DOOR ?	1.00	181.60		181.60
95	4	T67001-26302 PANEL SUB-ASSY, FR (RH Door) - 00	1.00	1904.50		1904.50
96	5	T68610-26041 CHECK ASSY, FR DOOR ?	1.00	185.90		185.90
97	6	T67861-26050 WEATHERSTRIP FR ?	1.00	232.60		232.60
98	7	T67610-26671 B0 RHBOARD ASSY, FR DOOR ?	1.00	812.10		812.10
99	8	T67620-26651 B0 L/FRT DOOR TRIM BOARD X	1.00	812.10		812.10
100	9	T67491-26050 GARNISH, FR DOOR LWR ?	1.00	68.70		68.70
101	0	T67492-26050 GARNISH, FR DOOR LWR ?	1.00	68.70		68.70
102	1	T68710-26022 R/FRT DOOR TOP HINGE, ?	1.00	111.30		111.30
103	2	T68730-26012 R/FRT DOOR LOW HINGE, ?	1.00	111.30		111.30
104	3	T71110-26011 FRAME ASSY, FR SEAT (Seat Frame) - BT (RH)	1.00	849.90		849.90
105	4	T71073-26A00 B2 COVER SUB-ASSY, FR - CUT (RH)	1.00	659.20		659.20
106	5	T71551-26270 PAD, FR SEAT BACK ?	1.00	399.50		399.50
107	6	T71074-26A00 B1 COVER SUB-ASSY, FR (LH) - CUT	1.00	659.20		659.20
108	7	T71551-26310 PAD, FR SEAT BACK ?	1.00	324.90		324.90
109	8	T90975-02086 TOYOTA SYMBOL EMBLEM, - n/c	1.00	72.20		72.20
110	9	T56101-26291 GLASS SUB-ASSY, - OR	1.00	1385.40		1385.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000019 / ICUOI1	M/S Sim Solutions Pte Ltd 126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355	
		Document No. 0		
		Document Date 06/09/2021	Mobile: 84372553	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
111	0	T56118-26020 DAM, WINDOW GLASS	1.00	18.70		18.70
112	1	T56117-26060 FRT W/SCREEN DAM KIT,	1.00	39.80		39.80
113	2	T56115-26060 STOPPER, WINDSHIELD	2.00	15.00		30.00
114	3	T75531-26071 FRONT W/SCREEN MLDG,	1.00	78.30		78.30
115	4	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00
116	5	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
117	6	T81130-26731 UNIT ASSY, HEADLAMP,	1.00	753.70		753.70
118	7	T81170-26731 UNIT ASSY, HEADLAMP,	1.00	753.70		753.70
119	8	T84340-49045 SWITCH ASSY, STOP	1.00	65.70		65.70
120	9	T88280-42010 SWITCH ASSY, CLUTCH	1.00	45.70		45.70
121	0	T85212-26051 R/FRT WIPER BLADE	1.00	84.80		84.80
122	1	T85211-26081 ARM, FR WIPER, RH	1.00	141.70		141.70
123	2	T85292-13010 FRT WIPER ARM CAP,	1.00	12.10		12.10
124	3	T85150-26110 FRONT WIPER LINK ASSY	1.00	399.00		399.00
125	4	T85110-26231 MOTOR ASSY, FR WIPER	1.00	893.80		893.80
126	5	T85222-26091 L/FRT WIPER BLADE	1.00	84.80		84.80
127	6	T85221-26071 ARM, FR WIPER, LH	1.00	170.70		170.70
128	7	T85292-13010 FRT WIPER ARM CAP,	1.00	12.10		12.10
129	8	T85315-26130 JAR, WASHER, A	1.00	185.20		185.20
130	9	T90446-07001 HOSE	1.00	15.50		15.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no. 6631 1168

ESTIMATE

Account Details		Account No.	Customer Details	
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000019 / ICUOI1	M/S Sim Solutions Pte Ltd	
		Document No. 0	126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355	
		Document Date 06/09/2021	Mobile: 84372553	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
131	0	T85336-12230 HOSE	2.00	12.40		24.80
132	1	T85381-26221 NOZZLE, FR WASHER,	2.00	41.40		82.80
133	2	T90446-07001 HOSE	1.00	15.50		15.50
134	3	T85349-89122 JOINT	2.00	4.40		8.80
135	4	T85348-12250 JOINT	1.00	2.90		2.90
136	5	T90446-07001 HOSE	1.00	15.50		15.50
137	6	T85330-21010 FRT WASHER JAR MOTOR,	1.00	295.80		295.80
138	7	T86520-20300 LOW-PITCHED HORN ASSY, (MARUKO)	1.00	135.50		135.50
139	8	T86591-26040 BRACKET, HORN	1.00	15.20		15.20
140	9	T87130-26220 A/C BLOWER ASSY	1.00	1003.40		1003.40
141	0	T87050-26200 AIR CONDENSOR RADIATOR	1.00	3655.10		3655.10
142	1	T87139-26010 ELEMENT, AIR REFINER	1.00	158.60		158.60
143	2	T88548-26070 CASE, AIR FILTER	1.00	33.30		33.30
144	3	T87114-26040 COVER, HEATER	1.00	81.60		81.60
145	4	T88482-26040 CAP, COOLER	1.00	3.30		3.30
146	5	T88650-26840 AMPLIFIER ASSY, AIR	1.00	953.60		953.60
147	6	T87121-26200 BRACKET, HEATER	1.00	24.30		24.30
148	7	T88717-2F681 TUBE, SUCTION, NO.1	1.00	626.10		626.10
149	8	T88716-2N121 TUBE, LIQUID, NO.1	1.00	345.50		345.50
150	9	T88715-26390 A/C DISCHARGE TUBE,	1.00	266.80		266.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUO11	M/S Sim Solutions Pte Ltd 126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355 Mobile: 84372553
	Document No. 0	
	Document Date 06/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
151	0	T88710-2F620 A/C TUBE & ACCESSORY, 1	1.00	123.70		123.70
152	1	T88450-26150 CONDENSER ASSY, 1	1.00	1968.30		1968.30
153	2	T88711-2F310 HOSE, DISCHARGE, 1	1.00	570.80		570.80
154	3	T88712-2F360 HOSE, SUCTION, 1	1.00	565.90		565.90
155	4	T88718-2F330 CLAMP, PIPING, 1	1.00	13.10		13.10
156	5	T88410-28200 CLUTCH ASSY, MAGNET, 1	1.00	1271.10		1271.10
157	6	T88440-35120 PULLEY ASSY, IDLE, 1	1.00	491.30		491.30
158	7	T88320-25110 COMPRESSOR ASSY, 1	1.00	2106.60		2106.60
159	8	T88431-35250 BRACKET, COMPRESSOR, 1	1.00	450.60		450.60
160	9	T17700-30282 CLEANER ASSY, AIR, 1	1.00	787.80		787.80
161	0	T17311-30050 AIR-INLET DUCT NO 1, 1	1.00	114.10		114.10
162	1	T17312-11010 DUCT, AIR INLET, 1	1.00	74.70		74.70
163	2	T17940-30051 INTERCOOLER ASSY, 1	1.00	1886.30		1886.30
164	3	T17945-30040 INTERCOOLER BRACKET, 1	1.00	69.90		69.90
165	4	T17750-30040 INLET ASSY, AIR, 1	1.00	113.40		113.40
166	5	T22204-30020 METER SUB-ASSY, 1	1.00	424.30		424.30
167	6	T17881-30150 HOSE, AIR CLEANER, 1	1.00	120.30		120.30
168	7	T17894-30020 RESONATOR, INTAKE, 1	1.00	70.50		70.50
169	8	T96111-10900 CLAMP, 1	1.00	3.70		3.70
170	9	T96111-10690 CLAMP***, 1	1.00	10.90		10.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUO11	M/S Sim Solutions Pte Ltd 126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355
	Document No. 0	Mobile: 84372553
	Document Date 06/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
171	0	T96111-10500 CLAMP	1.00	8.60		8.60
172	1	T17893-30060 RESONATOR, INTAKE	1.00	32.70		32.70
173	2	T17360-30050 PIPE ASSY, AIR	1.00	190.10		190.10
174	3	T17343-30023 HOSE, AIR, NO.3	1.00	313.00		313.00
175	4	T90460-67008 CLAMP, HOSE	2.00	15.40		30.80
176	5	T17362-30021 TUBE, AIR, NO.2	1.00	291.60		291.60
177	6	T17361-30021 TUBE, AIR, NO.1	1.00	291.60		291.60
178	7	T17342-30062 HOSE, AIR, NO.2	1.00	313.00		313.00
179	8	T16470-75124 RADIATOR RESERVE TANK	1.00	626.70		626.70
180	9	T16261-75230 HOSE, WATER BY-PASS	1.00	24.70		24.70
181	0	T16264-75170 HOSE, WATER BY-PASS	1.00	24.70		24.70
182	1	T16400-30163 RADIATOR ASSY	1.00	2604.90		2604.90
183	2	T16360-11300 FAN ASSY, W/MOTOR	1.00	7600.30		7600.30
184	3	T16058-30020 HOSE SUB-ASSY,	1.00	114.70		114.70
185	4	T16577-30021 PIPE, RADIATOR, NO.1	1.00	199.10		199.10
186	5	T16267-30130 HOSE, WATER BY-PASS,	1.00	46.10		46.10
187	6	T16573-30030 HOSE, RADIATOR, NO.3	1.00	45.70		45.70
188	7	T16578-30011 RADIATOR PIPE NO.2	1.00	151.40		151.40
189	8	T16574-30010 HOSE, RADIATOR, NO.4	1.00	49.40		49.40
190	9	T16307-30010 BRACKET SUB-ASSY,	1.00	74.10		74.10

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUOI1	M/S Sim Solutions Pte Ltd 126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355 Mobile: 84372553
	Document No. 0	
	Document Date 06/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
191	0	T16206-75010 PIPE SUB-ASSY, WATER	1.00	57.30		57.30
192	1	T96136-42101 CLIP, HOSE	2.00	9.20		18.40
193	2	T99555-20075 HOSE, WATER	1.00	6.60		6.60
194	3	T47110-V3010 SUPPORT ASSY, BRAKE	1.00	376.60		376.60
195	4	T47201-26811 CYLINDER SUB-ASSY,	1.00	847.00		847.00
196	5	T44610-26820 BOOSTER ASSY, BRAKE	1.00	1803.40		1803.40
197	6	T44785-12040 GASKET, BRAKE	1.00	9.70		9.70
198	7	T44774-26391 HOSE, UNION TO	1.00	54.10		54.10
199	8	T96133-41500 CLIP, HOSE	4.00	7.20		28.80
200	9	T44761-26420 TUBE, VACUUM PUMP TO	1.00	81.60		81.60
201	0	T44764-26180 TUBE, CONNECTOR TO	1.00	132.10		132.10
202	1	T89173-59275 SENSOR, AIR BAG, FR	1.00	378.00		378.00
203	2	T89173-59275 SENSOR, AIR BAG, FR	1.00	378.00		378.00
204	3	T89170-26400 SENSOR ASSY, AIR BAG	1.00	1073.90		1073.90
205	4	T73970-26050 B1 AIR BAG ASSY, INSTR	1.00	4249.30		4249.30
206	5	T45130-26370 B0 PAD ASSY, STEERING	1.00	2895.10		2895.10
207	6	T45107-22010 WIRE SUB-ASSY, HORN	1.00	8.60		8.60
208	7	T84306-12160 CABLE SUB-ASSY,	1.00	459.60		459.60
209	8	T82143-26022 WIRE, INSTRUMENT	1.00	29.00		29.00
210	9	T73210-26771 C0 BELT ASSY, FR SEAT,	1.00	1001.90		1001.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

Inc: 196700086Z
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUOI1	M/S Sim Solutions Pte Ltd 126 Joo Seng Road #05-07 Gold Pine Industrial Bldg Singapore 368355 Mobile: 84372553
	Document No. 0	
	Document Date 06/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	KDH201R	SBMDY S6	29/03/2021	GBL1879M	0	64579	72/OD/GBL1879M
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFHT02P200251615	1KDB071470	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
211	0	T73230-26241 C0 BELT ASSY, FR SEAT, (LH) - Jwd	1.00	152.10		152.10
212	1	T73220-26531 C0 BELT ASSY, FR SEAT,	1.00	1001.90		1001.90
213	2	T73240-26182 C0 BELT ASSY, FR SEAT,	1.00	127.20		127.20
214	3	T45260-26110 SHAFT ASSY, STEERING	1.00	626.10		626.10
215	4	T45297-26021 SHAFT, STEERING	1.00	348.30		348.30
216	5	T45250-2F430 COLUMN ASSY,	1.00	1029.60		1029.60
217	6	T45253-26151 COVER, STEERING	1.00	106.50		106.50
218	7	T45380-37020 GEAR ASSY, STEERING	1.00	1126.30		1126.30
219	8	T45312-26190 BRACKET, STEERING	1.00	54.40		54.40
220	9	T45209-26050 YOKE SUB-ASSY,	1.00	264.60		264.60
221	0	T45390-26190 SHAFT ASSY, STEERING	1.00	378.00		378.00
222	1	T45286-26400 B0 COVER, STEERING	1.00	96.20		96.20
223	2	T45287-26350 B0 COVER, STEERING	1.00	123.70		123.70
224	3	T45020-33151 BRACKET ASSY, STRG	1.00	516.90		516.90
225	4	T45271-16020 CLAMP	1.00	21.70		21.70
226	5	T44360-26150 RESERVOIR ASSY, OIL	1.00	437.40		437.40
227	6	T08889-01203 COOLANT, SLLC (BLUE)	2.00	129.10		258.20
228	7	TPIONR-1250H IACE AUDIO DEH-S1250UB W IMPROVED H	1.00	199.00		199.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
• To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Please acknowledge receipt of vehicle	Parts 81,741.70 Labour 246.00 Sublet 22,926.80 Lubrication/Fluid 0.00 Others 0.00	104,914.50 GST 7.00% 7,344.02 Less 0.00 Amount Due 112,258.52

Acknowledged by Repairer
Signature:
Date:

Customer Copy