

Veron Chen (LKKAUTO)

From: Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>
Sent: Monday, 13 September 2021 11:02 AM
To: Veron Chen (LKKAUTO); SUR
Cc: Steve Chen (LKK Auto)
Subject: RE: GBL 1879M-DOA: 6/9/21 (UOI OD)
Attachments: WhatsApp Image 2021-09-13 at 10.57.03.jpeg; WhatsApp Image 2021-09-13 at 10.57.02 (1).jpeg; WhatsApp Image 2021-09-13 at 10.57.02.jpeg

Dear Veron,

The said vehicle need to be total loss because the damaged on the chassis number is not allow to replace it. Kindly refer to attach photo.

Thank you

Regards

Thomas pang

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Thursday, 9 September 2021 11:39 am
To: SUR <sur@lkkauto.com>; Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>
Cc: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Subject: GBL 1879M-DOA: 6/9/21 (UOI OD)

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

Dear Thomas,

As instructed by our client , please proceed to repair the **insured vehicle GBL 1879M, Not Exceeding Repair Cost \$57,000/- or whichever lower, (Excess \$500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)