

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☒ / N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMQ 3881K

at Workshop m/s V-Tec Asia Auto

of _____

Insured: SMB 1587C

Policy No. _____


Claims No. BUS/09/21/5005

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$69k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMQ3881K Yr Regn: 13 Nov/2019

Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: HONDA FIT 1.3 c.c. 1317

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 23735 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK33417290

Gen. Cond ☒ Good ☐ Fair / Poor / BurntSteering: ☒ Inorder ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder ☐ Jammed / Leaked / Burnt orModi: ☒ Nil ☐ S/Rim / STD A/Rim or

Tyre Size: F: 175/70R14

R: 175/70R14

BS ☒ DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 08-09-2021

Survey held at W/S 12:30PM

Des. of Damages: Frt / ☒ Rea ☐ / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Guo Qiang finalised LS \$2550, 4 days. (Red \$8150, 76%)

Date/Time, File Pass to?

☐ : Preli. Report

1) 22/03 Typist

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Filed: TP

Lump Sum / Fee: 2550

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)☐ : W/Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL