



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4 Premier @ #07-08 544154751
Tel: 64352 7006 Reg No: 2015 34887R



Vehicle No : 5MQ3881K

ACCIDENT CAR REPAIR ESTIMATIONS

S/No.	Qty	Parts Descriptions	Condition	Per Unit	Our Estimates
1	1 pc	Replace New Rear Boot	— One		\$1,600.00
2	1 pc	Rear New Windscreen	— CRA		\$1,280.00
3	1 pc	Replace New Rear Bumper	— Le		\$1,800.00
4	2 pc	Honda & Fit Emblems	— all		\$120.00
5	2 pc	Reverse Sensor	X	} NN	\$480.00
6	1 pc	Reverse Camera	X		\$180.00
7	1 pc	Rear Door Locking System	X		\$480.00
8	2 pc	Rear Door Absorber Hinge	X		\$400.00
9	1 pc	Weather Strip	X		\$280.00
10	1 pc	Tailgate Outer Garnish New	— CRA		\$450.00
11	1 pc	Lower Bumper Spoiler	X	} NN	\$380.00
12	1 pc	Rear Reinforcement	X		\$980.00
Parts Total :					\$8,430.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4 Days.

Complete repair

After repair photos.

Guo Q: ang

8288 0282

Guo Q: ang @ lkkauto.com

8/9/2021



V-TEC ASIA AUTOMOTIVE PTE LTD

8 Kaki Bukit Ave 4 Premier @ KB #07-08 S(415875)
Tel: 66352 706 Reg No: 2015 34887R



Vehicle No : SMQ3881K

LABOUR ESTIMATIONS

S/No.	Labour Descriptions	Our Estimates
1	Labour for remove and installation of damaged & affected Parts Rear Bumper and Rear Boot and Windscreen & Necessary Parts	\$950.00 400
1	Spray Painting to Rear Bumper, Rear Boot & Tailgate Outer Garnish & Necessary Parts	\$850.00 400
3	Diagnostic To Vehicle & Electrical System	\$250.00 30
4	Rewiring Of Camera	\$220.00 30

Labour Total :	\$2,270.00
Parts Total :	\$8,430.00
Total (Parts & Labour) :	<u>\$10,700.00</u>

For Lump Sum Repairs

The estimated amount calculated is \$10,700.00

Under normal circumstances, the repairs should be completed within a reasonable period
Of 7 Working Days. (Exclude waiting days of PRI, Sunday and Public Holiday)