

06/09/2021

1st



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SNA3005XMake & Model : TOYOTA COROLLAYear of Manufacture : 2020Chassis No. : MR2BE3BE800011986

Engine No. : _____

Policy No. : _____

Time of Accident : _____

Ins Company : III VS CNTP

Excess : _____

Date of Accident : 9/1/2021

Suggested Days of Repair : _____

In-house Vehicle Assessor

Case Owner : _____

Signature : _____

Contact No
Frt Counter OperationBrenda Tel: 63837730 email: brendang@sparkcarcare.com
Rohani tel: 63837890 email: rohanim@sparkcarcare.com**Back-end Operation**Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com
Patrick Tel: 63837466 email: patricktia@sparkcarcare.com**Repair Estimates**Parts (a) Cost / List Price Items \$ 5,946.00Plus/Less 25% \$ 1,486.50Total of Cost / List \$ 4,459.50(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 295.00Total Parts Cost (Appendix A) \$ 4,754.50Labour (Appendix B) \$ 2,320.00Total Repair Cost \$ 7,074.50

The above total will be subjected to 7% G.S.T.

Not authorized
Resurvey B4 paint
86077.79

Name of Surveyor : KennethCompany : CKICSurvey conducted on : 7/9/21 at 3.10pm**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 07 day(s)(c) Resurvey : Required / Not Required Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 7/9/21

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Page 1

Spare Parts

Vehicle No : SNA3005X Case Owner : 0
Make & Model : TOYOTA COROLLA Year Manufacture : 2020
Chassis No : MR2BE3BE800011986 Engine No : 0
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	BOOTLID <i>By</i>	1		\$ 890.00			<i>✓</i>
2	BOOTLID LOCK <i>De</i>	1		\$ 256.00			<i>✓</i>
3	BOOTLID INNER TRIM <i>Di</i>	1		\$ 260.00			<i>✓</i>
4	BOOTLID LAMP LH <i>Pl</i>	1		\$ 300.00			<i>✓</i>
5	BOOTLID LAMP RH <i>Pl</i>	1		\$ 300.00			<i>✓</i>
6	BOOTLID LOGO <i>Ne</i>	1		\$ 60.00			<i>✓</i>
7	BOOTLID EMBLEM COROLLA <i>Ne</i>	1		\$ 79.00			<i>✓</i>
8	BOOTLID EMBLEM ALTIS <i>Ne</i>	1		\$ 79.00			<i>✓</i>
9	BOOTLID HINGE LH <i>R</i>	1		\$ 135.00			<i>X</i>
10	BOOTLID HINGE RH <i>R</i>	1		\$ 135.00			<i>X</i>
11	BOOTLID CHROME <i>Pl</i>	1		\$ 234.00			<i>X</i>
12	TAILLAMP LH <i>CV</i>	1		\$ 345.00			<i>✓</i>
13	TAILLAMP RH <i>CV</i>	1		\$ 345.00			<i>✓</i>
14	REAR BUMPER <i>By</i>	1		\$ 434.00			<i>✓</i>
15	REAR BUMPER SIDE RETAINER LH <i>CM</i>	1		\$ 104.00			<i>✓</i>
16	REAR BUMPER SIDE RETAINER RH <i>Di</i>	1		\$ 104.00			<i>✓</i>
17	REAR BUMPER SENSOR X2 <i>Shut</i>	1		188.30	<i>✓</i>	\$ 250.00	<i>2020</i>
18	REAR BUMPER SENSOR HOLDER X2 <i>NN</i>	1		TBA			<i>X</i>
19	REAR BUMPER UNDER COVER <i>CM</i>	1		\$ 455.00			<i>✓</i>
20	REAR BUMPER CLIPS <i>Ne</i>	6		\$ 30.00			<i>✓</i>
21	REAR BUMPER TOW COVER <i>De</i>	1		\$ 45.00			<i>✓</i>
22	REAR END PANEL <i>By</i>	1		\$ 533.00			<i>✓</i>
23	REAR END PANEL TOP GARNISH <i>Di</i>	1		\$ 278.00			<i>✓</i>
24	REAR NUMBER PLATE <i>De</i>	1				\$ 45.00	<i>✓</i>
25	SPARE TYRE TOP BOARD <i>Return</i>	1		\$ 545.00			<i>✓</i>
0		0					
0		0					
0		0					
0		0					
0		0					

If any of the quoted parts are recommended to be repaired, then an additional labour charge be charged accordingly under supplementary.

06/09/2021

10:06 AM

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No.	: <u>SNA3005X</u>	Case Owner	: <u>0</u>
Make & Model	: <u>TOYOTA COROLLA</u>	Year of Manufacture	: <u>2020</u>

The above estimate of repair is based on visual assessment of the external affected areas. Any onal damages observed during the course of repair will be quote accordingly as a supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Supplementary 1

Vehicle No : SNA3005X Case Owner : 0

Make & Model : TOYOTA COROLLA Year Manufacture : 2020

Chassis No : MR2BE3BE800011986 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	TAILLAMP SIDE COVER LH	1	<i>RM</i>	\$ 79.54			<i>✓</i>
2	TAILLAMP SIDE COVER RH	1	<i>RM</i>	\$ 79.54			<i>✓</i>
3	TAILLAMP LOWER BRACKET RH	1	<i>RM</i>	\$ 79.54			<i>✓</i>
4	TAILLAMP SIDE CLIP LH	1	<i>CM</i>	\$ 10.00			<i>✓</i>
5	TAILLAMP SIDE CLIP RH	1	<i>CM</i>	\$ 10.00			<i>✓</i>
6	BOOLID WEATHER STRIP	1	<i>RM/GR</i>	\$ 244.32			<i>✓</i>
7	REAR BUMPER REINFORCEMENT	1	<i>RM</i>	\$ 287.14			<i>✓</i>
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care