

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP 7220Y

LAD2109-004

Not Withheld

Pulung B4poin

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

07 SEP 2021

SMP7220Y

MR053REH604598923

TOYOTA

COROLLA ALTIS

5.9.2021

LONPAC

11/10/2019

PART	LIST
1 COVER, FRONT BUMPER	\$ B1/LM 531.10 ✓
1 SUPPORT, FRONT BUMPER SIDE, LH	\$ D1/L 68.20 ✓
1 SUPPORT, FRONT BUMPER SIDE, RH	\$ D1/R 68.20 ✓
1 ABSORBER, FRONT BUMPER ENERGY	\$ 111.80 ?
1 REINFORCEMENT, FRONT BUMPER	\$ 399.50 ?
1 COVER, FRONT BUMPER HOLE, RH	\$ M1 209.40 ?
1 GRILLE, RADIATOR, LOWER NO. 1	\$ M1 169.60 ✓
1 GRILLE SUB-ASSY, RADIATOR	\$ CM 712.10 ✓
1 EMBLEM, RADIATOR GRILLE	\$ M1 47.90 ✓
1 COVER, RADIATOR	\$ D1/L 80.70 ✓
1 COVER, ENGINE UNDER, CENTER	\$ 179.40 ?
1 HOOD SUB-ASSY	\$ B1 1,248.80 ✓
1 LOCK ASSY, HOOD	\$ D1/R 135.00 ✓
1 INSULATOR, HOOD	\$ L 280.10 X
1 HINGE ASSY, HOOD, RH	\$ R 58.90 X
1 HINGE ASSY, HOOD, LH	\$ R 58.90 X
1 HEADLAMP ASSY, RH	\$ L 2,487.80 ✓
1 HEADLAMP ASSY, LH	\$ M1/R 2,487.80 ✓
1 BRACE, HOOD LOCK SUPPORT	\$ 164.90 ?
1 SUPPORT SUB-ASSY, RADIATOR, RH	\$ 211.00 ?
1 SUPPORT SUB-ASSY, RADIATOR, LH	\$ 211.00 ?
1 SUPPORT SUB-ASSY, RADIATOR, UPPER	\$ R 277.30 X
1 DEFLECTOR, RADIATOR SIDE, RH	\$ L 80.70 X
1 JAR ASSY, WINDSHIELD WASHER	\$ L 219.10 X
1 MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$ L 293.00 X
1 INLET, AIR CLEANER, NO. 1	\$ L 191.50 X
1 RESONATOR, INTAKE AIR	\$ L 107.00 X

Trans-cab Auto Services Pte Ltd**LAD2109-004**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP 7220 Y

TOTAL	\$	11,090.70
25%	\$	2,772.68
	\$	8,318.03

Special Nett

1SET FRONT LH FENDER LINER CLIP	\$	nn	70.00	X
1SET FRONT RH FENDER LINER CLIP	\$	nn	70.00	X
1SET BUMPER CLIP FRT	\$	nn	80.00	5050
1SET FRONT LH BUMPER SUPPORT CLIP	\$		70.00	7
1SET FRONT RH BUMPER SUPPORT CLIP	\$		70.00	7
1 RADIATOR GRILLE CLIP	\$	nn	60.00	✓
1 RADIATOR COVER CLIP	\$	nn	60.00	✓
1SET Front Licence Plate Number With Holder	\$	nn	200.00	4550
1 HOOD INSULATOR CLIP	\$	nn	55.00	X

TOTAL \$ 735.00**TOTAL PARTS \$ 9,053.03****LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 3,500.00 5000

Putty And Spray Painting Of The Affected Portion.

\$ 3,500.00 6600

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 200

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 300

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP 7430 y

To transfer of Front Bumper fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To transfer of Front Bonnet fittings, attachments and perform water seepage test.

\$ *nn* 170.00 X

TOTAL \$ 8,530.00

Over All Total \$ 17,583.03

(PART-BY-PART) Repair Days

14 days

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: