

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L
 G S T : 5 3 3 6 0 0 6 1 L

Handler - JWS/11/17

Steve CLKK)
 9/9/21, 10.32am

WML R
 L/S
 M AL by
 4 days

QT21/XE6227M/TPC

AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way
#07-16
Singapore 079120

QUOTATION

Dear Sir,

Cost of Repair to Vehicle XE6227M


With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front bumper Chrome SN / BT	1	4,328.00	4,328.00
2.	Front bumper bracket LH ?	1	389.67	389.67
3.	Front bumper LH rubber guard / TN	1	330.20	330.20
4.	Front bumper inner structure ?	1	950.00	950.00
5.	Front grille lower Chrome SN / BR	1	1,860.00	1,860.00
6.	LH corner side lower guard / CVT	1	549.37	549.37
7.	LH passenger door step outer guard chrome SN / CVT	1	945.97	945.97
8.	LH step garnish outer panel X R	1	920.00	920.00
9.	Check wiring	1	30.00	30.00
10.	Labour charges	1	1,200.00	1,200.00
11.	Spray painting	1	200.00	200.00
SUB-TOTAL				S\$11,703.21

- Price before 7% gst

Thank you.

Yours faithfully,



Winnie Chai

HP: 9850-9666



LKK Auto Consultancy to ensure notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: