

159 TICK HAI MOTOR
1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 53033608A

*not Adhwal
 have
 20/9/21*

*2/58 1600
 shayla shayla
 3 bay*

Vehicle Number: GX6470C
 Vehicle Model : Toyota Dyna 150D
 Manufacturing Year: 2004
 Chassis : JTFUF34Y403002566

S/N	Item Description	Amount (\$)
1	Headlamp (RH) o/s <i>scr/line</i> <i>645-30</i>	\$ 1,214.48
2	Front Bumper <i>pus</i>	\$ 375.40
3	Front Grille <i>one</i>	\$ 448.69
4	Front Door (RH) o/s <i>R</i>	\$ 1,487.80
5	Front Door Weatherstrip (RH) o/s <i>11</i>	\$ 195.60
6	Step Garnish (RH) o/s <i>one</i>	\$ 287.40
7	Front Corner Panel (RH) o/s <i>one</i>	\$ 199.75
Total :		\$ 4,209.12
Less 25% :		\$ 1,052.28
Amount :		\$ 3,156.84

S/N	Special Nett Item	Amount (\$)
1	Side Marking <i>Roc sticker o/s</i> <i>one</i>	\$ 25.00
2	Door Company Sticker <i>o/s</i> <i>one</i>	\$ 120.00
Total :		\$ 145.00

Labour		Amount (\$)
To check front electrical wiring system		\$ 50.00
To transfer door components from old door to new door		\$ 11 120.00
To straighten, repair, realign on affected area and replace damaged parts		\$ 950.00
To spray painting on affected area		\$ 980.00
1 KK Auto Consultants hereby notify the Repairer of the following:		
- To resurvey work order spray painting - To disassemble (headlamp part's) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - Malicious modification is allowed		
Labour Total :		\$ 2,100.00
Total (Parts & Labour)		\$ 5,401.84

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*2-1489.39
 25%
 P-1102.04
 S.N-145.00
 L-800.00
 2047.04*