

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: **GX 6470C**  
 at Workshop m/s: **Ticke;**  
 of \_\_\_\_\_  
 Insured: **SKS 6166K**  
 Policy No. **DMPCSNW00161842100**  
 Claims No. **SNM21D204968/C02/TANKL**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**  
 Bal. or Market Value: **\$18k.**  
 IDAC Accident Rport: Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: **3** days Res.: Yes or No  
 Lum Sum: **22** % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS **\$63k**  
 Date: \_\_\_\_\_ Person Contacted: **Rep 6k plus.**

N/S	O/S

Veh No: **GX 6470C** Yr Regn: **03/08/04**  
 Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**  
**Truck / Trailer or (M / ISO D**  
 Make: **Toyota Dyna** 2986  
 Colour: **S.W** A/C: **Insured / Std / NI / NA**  
 Sp.Reading: **214603** T/Radio: **Insured / Std / NI / NA**  
 Eng/No: \_\_\_\_\_  
 C/No: **JTFUF344403002566**  
 Gen. Cond: **Good / Fair / Poor / Burnt**  
 Steering: **In order / Jammed / Leaked / Burnt or**  
 Brake: **In order / Jammed / Leaked / Burnt or**  
 Modi: **Nil / S/Rim / STD A/Rim or**  
 Tyre Size: **F: 185 R14**  
**R: 155 R12**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **habited**  
 Front          Rear           
 R/Bal. **6** mm R/Bal. **6/6** mm  
 L/Bal. **6** mm L/Bal. **6/6** mm  
 D.O.A. **11/9/21** D.O.I. **20/9/21**  
 Survey held at \_\_\_\_\_  
 Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop or**  
**0.5 Ref.**  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
**23/9/21 1/5 @ 1600 confirmed with Robert (Red 3801.84, 70%)**  
**We until 31-7-2024 @ 7547**

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:   
 Transportation:   
 ) \_\_ \$ + RS \_\_ \$  
 ) Photos  
 ) Others  
 )  
 )  
 TOTAL

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Report Format : Merimen  
 Lump Sum / I.B. : (\$ 1600 )

not Adhond  
Lau  
20/9/21  
1/58 1600  
shyphel Abang  
3 bay

**159 TICK HAI MOTOR**  
**1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883**  
**TEL: 6842 9089 FAX: 6841 2869**  
**REG NO : 53033608A**

Vehicle Number: GX6470C  
 Vehicle Model : Toyota Dyna 150D  
 Manufacturing Year: 2004  
 Chassis : JTFUF34Y403002566

S/N.	Item Description	Amount (\$)
1	Headlamp (RH) o/s <i>scnlone 645-30</i>	\$ 1,214.48
2	Front Bumper <i>Dos</i>	\$ 375.40
3	Front Grille <i>one</i>	\$ 448.69
4	Front Door (RH) o/s <i>R</i>	\$ 1,487.80
5	Front Door Weatherstrip (RH) o/s <i>1 1</i>	\$ 195.60
6	Step Garnish (RH) o/s <i>one</i>	\$ 287.40
7	Front Corner Panel (RH) o/s <i>1 1</i>	\$ 199.75
<b>Total :</b>		<b>\$ 4,209.12</b>
<b>Less 25% :</b>		<b>\$ 1,052.28</b>
<b>Amount :</b>		<b>\$ 3,156.84</b>

1 set  
1 set

S/N	Special Nett Item	Amount (\$)
1	Side Marking <i>Roc sticker o/s</i>	\$ 25.00
2	Door Company Sticker <i>o/s</i>	\$ 120.00
<b>Total :</b>		<b>\$ 145.00</b>

Labour	Amount (\$)	
To check front electrical wiring system	\$ 50.00	
To transfer door components from old door to new door	\$ 11 120.00	
To straighten, repair, realign on affected area and replace damaged parts	\$ 950.00	
To spray painting on affected area	\$ 980.00	
<b>Labour Total :</b>		<b>\$ 2,100.00</b>
<b>Total (Parts &amp; Labour)</b>		<b>\$ 5,401.84</b>

I/KK Auto Consultants hereby notify  
 the Repairer of the following:

- To resurvey damaged area after spray painting
- To disclose (if/when) part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- All financial transactions to be allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

2-1489.39  
 25%  
 P-1102.04  
 S-N-145.00  
 L-800.00  
 2147.04