LETTER OF UNDERTAKING

FOR THE REPAIR OF VEHICLE NO. YP 355X .

We, the undersigned, confirm that we will undertake to repair the vehicle bearing	
Registration No <u>YP 355X</u> to its pre-acci	dent condition, and to the satisfaction of its
owner, at a total cost not exceeding/not more the	nan Lump Sum \$25,000.00 (before
excess)subject to no breach of Terms & Condition of the POLICY, and to the legal	
requirement of the local Land Transport Authority (LTA).	
There should be no further supplementary to the repair cost.	
The repair job should not be exceeding <u>NA</u> days to complete the entire repair.	
10 9 2021 Date	Workshop Stamp/ Signature
10/09/2021	RASUL
Date	Witness by surveyor