

ASS. REC. BY:

Tang JH

REF:

CS/TM/21009415/TIVF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

WP

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Always

Veh No: SHA 38296Yr Regn: 296, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140c.c. 1685Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 671408

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: km HLB414M-G485547

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 8/9/21 e1040Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/O / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.H. (C) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
Policy No:
Vehicle Reg. No.: **SHA3829G**
Party At Fault: UNKNOWN

Ref. No:
Date of Loss: 06/09/2021
Driveable? YES

Make/Model: HYUNDAI I40, 1.7 L CRDI AT ABS
AIRBAG 4DR (A)
Vehicle Colour: BLUE
Engine No: D4FDDU395833
Odometer: 671408 KM

Vehicle Reg. Date: 10/03/2016
Gen Condition: GOOD
Chassis No: KMHLB41UMGU085547

Paint Type:
List Item Discount: 20.00 %
Total Loss? **NO**
Est. Duration of Repair (day) 3

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

Parts
Miscellaneous Items
Labour
Paintwork Labour
Towing

Amount

1,133.68
11.00
870.00
0.00
0.00

Gross Total (S\$) 2,014.68

+ GST 7.00% (S\$) 141.03

Nett Amount (S\$) 2,155.71

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 07 Sep 2021)**Parts:** 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA3829G/07/09/2021 13:51**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00 <i>de</i>	*553.00 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00 <i>neg</i>	*22.00 FL
3	1		*REAR BUMPER LOWER COVER	20.00	0.00 <i>X</i>	*228.00 FL
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00 <i>?</i>	*428.40 FL
5	1		*REAR REVERSE SENSOR	20.00	0.00 <i>nu</i>	*135.70 FL
6	1		*REAR BUMPER MAT	20.00	0.00 <i>nu</i>	*50.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,417.10
- List Item Discount on L Items (S\$)	283.42
Total Parts (S\$)	1,133.68

ComfortDelGro Engineering Pte Ltd/SHA3829G/07/09/2021 13:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			11.00
1	1	OD/TP Case (Insurer)	
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	280 450.00
2	SPRAY PAINTING	New	250 300.00
3	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
4	TUFF COATING	New	X 60.00
Gross Labour Cost (\$\$)			870.00

ComfortDelGro Engineering Pte Ltd/SHA3829G/07/09/2021 13:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495749
wp' 9/9/21 @ 10:40
c/s Resurvey after repair
02 days
Tanpin 11/09/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: