



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

TP AXA
Justin

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBM8431U YAMAHA RXZ 135 REPAIR ESTIMATE (08SEP2021)

ITEM	DESCRIPTION	AMOUNT (SGD)
1	TAIL COVER <i>cracked</i>	\$80.00 ✓
2	TAILLAMP <i>cut</i>	\$120.00 ✓
3	REAR LICENCE PLATE <i>cracked</i>	\$25.00 ✓
4	CHAIN GUARD <i>cracked</i>	\$28.00 ✓
5	REAR ABSORBER <i>Best</i>	\$240.00 ✓
6	REAR ARM <i>cracked</i>	\$295.00 ✓
7	ARM BEARING SET <i>Nec</i>	\$75.00 ✓
8	ADJUSTER SCREW <i>Best</i>	\$25.00 ✓
9	ADJUSTER PLATE <i>Dmgd</i>	\$18.00 ✓
10	SEAT LOCK <i>Dmgd</i>	\$48.00 ✓
11	SIDE FAIRING LH <i>cracked</i>	\$65.00 ✓
12	REAR FOOTREST LH <i>cut</i>	\$38.00 ✓
13	FRONT FOOTREST LH <i>shot</i>	\$48.00 +
14	FRONT FOOTREST BRACKET LH <i>Nec</i>	\$85.00 +
15	REAR WHEEL ASSY <i>warpped</i>	\$280.00 ✓
16	WHEEL BEARING X2 <i>Nec</i>	\$60.00 ✓
17	EXHAUST <i>Dented</i>	\$390.00 ✓
18	HEAT PROTECTION <i>Dented</i>	\$18.00 ✓
19	GASKET EXHAUST <i>den</i>	\$6.00 ✓
20	MAINSTAND <i>shot</i>	\$85.00 +
21	REAR FOOTREST RH <i>shot</i>	\$38.00 +
22	FRONT FOOTREST RH <i>cut</i>	\$48.00 ✓
23	FRONT FOOTREST BRACKET RH <i>shot Best</i>	\$85.00 ✓
24	BRAKE PEDAL <i>Best</i>	\$65.00 ✓
25	KICK STARTER <i>shot</i>	\$80.00 +
26	ENGINE COVER <i>cut</i>	\$125.00 ✓
27	HORN <i>shot</i>	\$60.00 +
28	HANDLEBAR RH <i>shot</i>	\$85.00 ✓
29	HANDLEGRIP <i>shot</i>	\$40.00 +
30	BALANCER <i>cut</i>	\$36.00 ✓
31	FRONT BRAKE PUMP <i>cut</i>	\$195.00 ✓
32	FRONT SIGNAL RH \$48 <i>shot</i>	\$48.00 ✓
33	SIDE MIRROR <i>shot</i>	\$50.00 +



潘發展私人有限公司
A. S. PHOON PTE LTD
'cos no one else

Head Off : 399, Changi Road S'pore 419846. Tel: (65) 6747 0770 Fax: (65) 6841 1263
Ubi : Blk 3007 #01-432/436 Ubi Road 1, S'pore 408701. Tel: (65) 6744 0770 Fax: (65) 6742 0250
Toh Guan : Blk 36 Toh Guan Road East #01-35 S'pore 608580 Tel: (65) 6515 0770 Fax: (65) 6515 0779
Website : www.asphoon.com Email: Enquiry@asphoon.com Co Reg No: 197701213H

FBM8431U YAMAHA RXZ 135 REPAIR ESTIMATE (08SEP2021)

ITEM	DESCRIPTION	AMOUNT (SGD)
32	FRONT WHEEL AXLE <i>lt.</i>	\$35.00 ✓
33	FRONT FENDER <i>Rejs</i>	\$68.00 <i>x.</i>
34	FRONT COWLING <i>cut</i>	\$125.00 ✓
35	WINDSHIELD <i>crackd</i>	\$32.00 ✓
36	COWLING BRACKET X2 @ \$18 <i>not in</i>	\$36.00 <i>x.</i>
37	FRONT LICENCE PLATE <i>new</i>	\$15.00 -
38	HEADLAMP	\$120.00 <i>x.</i>
39	HEADLAMP STAY <i>new</i>	\$85.00 <i>x.</i>
40	METER ASSY <i>new</i>	\$520.00 ✓
41	STAY METER <i>not in</i>	\$25.00 <i>x.</i>
42	TO RE-ALIGNMENT FRONT FORK AND STEERING STEM	\$250.00 <i>150.</i>
43	CONE BEARING SET <i>new</i>	\$65.00 ✓
44	FUEL TANK <i>not in</i>	\$390.00 <i>x.</i>
45	WORKMANSHIP	\$450.00 <i>250</i>
46	TRANSPORTATION TP-IDAC-BIKESHOP	\$100.00 <i>60.</i>
47	BODY CHASSIS REPAIR	\$400.00 <i>x.</i>
48	TRANSPORTATION X2 @ \$50	\$100.00 <i>x.</i>
TOTAL		\$5,800.00

Spray Painting. 150 ✓
slg.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian King.

L/S 09/09/21.

64 Days.

96893735

total: 3556

L/S: 2850