



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200151

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 07/01/2022  
Reference CC4/FCI21009425/Ara3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. SKV 9547J  
Insured Veh. GBE 7726T  
Claim No. D21002510MFCV/1  
Policy No. D-21097582MFCV  
Accident Date 04/09/2021  
Inspection Date 07/09/2021

| Description         | Total         |
|---------------------|---------------|
| Survey Inspection   | 917.00        |
| Resurvey Inspection |               |
| Digital Photographs |               |
| Transportation      |               |
| Less: Discount      | -337.00       |
| <b>Subtotal</b>     | <b>580.00</b> |
| <b>GST (7%)</b>     | <b>40.60</b>  |
| <b>Grand Total</b>  | <b>620.60</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                         |                 |                             |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------|-----------------------------|--|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                |                                                                                         |                 | Ref: CC4/FCI21009425/Ara3q2 |  |
|                                                                                                                                        |                                                                                         |                 | Date: 07/01/2022            |  |
|                                                                                                                                        |                                                                                         |                 | Code: FCI2                  |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                         |                 |                             |  |
| Insured Veh.                                                                                                                           | GBE 7726T                                                                               | Veh. Inspected  | SKV 9547J                   |  |
| Policy No.                                                                                                                             | D-21097582MFCV                                                                          | Coverage (\$)   | 0.00                        |  |
| Claim No.                                                                                                                              | D21002510MFCV/1                                                                         | Excess (\$)     | 0.00                        |  |
| Assign From                                                                                                                            | RACHEL WU                                                                               | Assign Date     | 07/09/2021                  |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                         |                 |                             |  |
| Make & Model                                                                                                                           | TOYOTA ALTIS                                                                            | c.c             | 1598                        |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                  | Year of Reg.    | 2015                        |  |
| Chassis No.                                                                                                                            | MR053REH104541723                                                                       | Colour          | WHITE                       |  |
| Odometer                                                                                                                               | 133013 KM                                                                               | Steering        | IN ORDER                    |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                | Modification    | SPORTS RIM                  |  |
| General                                                                                                                                | GOOD                                                                                    |                 |                             |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                         |                 |                             |  |
|                                                                                                                                        | Size                                                                                    | Make            | Balance                     |  |
| R/H Front Tyre                                                                                                                         | 205/55 R16                                                                              | DUNLOP          | 6 mm                        |  |
| L/H Front Tyre                                                                                                                         | 205/55 R16                                                                              | DUNLOP          | 6 mm                        |  |
| R/H Rear Tyre                                                                                                                          | 205/55 R16                                                                              | DUNLOP          | 6 mm                        |  |
| L/H Rear Tyre                                                                                                                          | 205/55 R16                                                                              | DUNLOP          | 6 mm                        |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                         |                 |                             |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.<br>DAMAGES SEE DETAILS.                                                   |                                                                                         |                 |                             |  |
| <b>5. General Information</b>                                                                                                          |                                                                                         |                 |                             |  |
| Accident Date                                                                                                                          | 04/09/2021                                                                              | Inspection Date | 07/09/2021                  |  |
| Survey held at                                                                                                                         | XIN HUA WORKSHOP PTE LTD<br>23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933 |                 |                             |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                         |                 |                             |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                         |                 |                             |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                         |                 |                             |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                         |                 | 24 Working Days             |  |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 9547J

| Qty | Description of Parts                   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------|---------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>     |               |                           |                   |
| 1   | BONNET                                 | DISTORTED     | 1,213.10                  | 1,213.10          |
| 1   | BONNET INNER RUBBER                    | CUT           | 56.20                     | 56.20             |
| 1   | BONNET INSULATOR CLIP                  | NECESSARY     | 40.00                     | 40.00             |
| 1   | BONNET LOCK                            | DAMAGED       | 131.10                    | 131.10            |
| 2   | HEAD LAMP HID @\$2816.10               | CRACKED       | 5,632.20                  | 5,632.20          |
| 2   | HEAD LAMP TOP CHROME @\$239.00         | NOT NECESSARY | 478.00                    | -                 |
| 2   | SET HEAD LAMP CLIP @\$30.00            | NOT NECESSARY | 60.00                     | -                 |
| 1   | FRONT GRILLE ASSY                      | CRACKED       | 625.00                    | 625.00            |
| 1   | FRONT GRILLE TOP RUBBER                | CUT           | 42.10                     | 42.10             |
| 1   | FRONT GRILLE BADGE                     | NECESSARY     | 95.80                     | 95.80             |
| 1   | FRONT GRILLE TOP GARNISH               | DEFORMED      | 158.60                    | 158.60            |
| 1   | FRONT GRILLE TOP GARNISH CLIP          | NECESSARY     | 30.00                     | 30.00             |
| 1   | FRONT BUMPER                           | DISTORTED     | 682.50                    | 682.50            |
| 2   | FRONT BUMPER SIDE RETAINER @\$83.30    | NECESSARY     | 166.60                    | 166.60            |
| 1   | SET FRONT BUMPER CLIP                  | NECESSARY     | 50.00                     | 50.00             |
| 1   | FRONT BUMPER REINFORCEMENT             | DENTED        | 386.60                    | 386.60            |
| 1   | FRONT BUMPER SPONGE                    | NOT NECESSARY | 129.20                    | -                 |
| 1   | FRONT BUMPER LOWER GRILLE              | NOT NECESSARY | 196.50                    | -                 |
| 2   | FRONT BUMPER FOGLAMP COVERS @\$145.20  | NOT NECESSARY | 290.40                    | -                 |
| 2   | FRONT BUMPER FOGLAMP @\$245.30         | NOT NECESSARY | 490.60                    | -                 |
| 2   | FRONT FENDERS @\$658.30                | N/S BUCKLED   | 1,316.60                  | 658.30            |
| 2   | FRONT FENDERS INNER COWLING @\$165.30  | NOT NECESSARY | 330.60                    | -                 |
| 1   | SUPPORT PANEL                          | DISTORTED     | 1,097.10                  | 1,097.10          |
| 1   | BRACE PANEL                            | BENT          | 145.20                    | 145.20            |
| 1   | RADIATOR                               | BENT          | 1,800.00                  | 1,800.00          |
| 2   | RADIATOR TOP MOUNTING @\$24.00         | NOT NECESSARY | 48.00                     | -                 |
| 2   | RADIATOR TOP MOUNTING BRACKET @\$50.00 | NOT NECESSARY | 100.00                    | -                 |
| 1   | AIR CON CONDENSER                      | BENT          | 1,507.40                  | 1,507.40          |
| 1   | CONDENSER AIR CON PIPE                 | NOT NECESSARY | 631.60                    | -                 |
| 1   | BOOT LID                               | DISTORTED     | 998.00                    | 798.00            |
| 1   | BOOT LID BADGE                         | NECESSARY     | 95.20                     | 95.20             |

Report Ref No. CC4/FCI21009425/Ara3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty | Description of Parts                       | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------|---------------|---------------------------|-------------------|
| 1   | BOOT LID EMBLEM COROLLA                    | NECESSARY     | 93.10                     | 93.10             |
| 1   | BOOT LID EMBLEM ALTIS                      | NECESSARY     | 93.60                     | 93.60             |
| 1   | BOOT LID OUTER CHROME MOULDING             | CRACKED       | 352.00                    | 223.00            |
| 1   | SET BOOT LID OUTER CHROME MOULDING CLIPS   | NECESSARY     | 30.00                     | 20.00             |
| 2   | BOOT LID NUMBER PLATE LAMP @\$72.10        | NOT NECESSARY | 144.20                    | -                 |
| 1   | BOOT LID OPENER SWITCH                     | NOT NECESSARY | 156.70                    | -                 |
| 2   | BOOT LID LAMP @\$457.20                    | CRACKED       | 914.40                    | 580.00            |
| 2   | BOOT LID LAMP INNER SEALER @\$40.00        | NECESSARY     | 80.00                     | 40.00             |
| 2   | SET BOOT LID LAMP CLIPS @\$25.00           | NOT NECESSARY | 50.00                     | -                 |
| 4   | BOOT LID STOPPER @\$25.00                  | NOT NECESSARY | 100.00                    | -                 |
| 1   | BOOT LID INSULATOR                         | DEFORMED      | 368.50                    | 285.00            |
| 1   | SET BOOT LID INSULATOR CLIPS               | NECESSARY     | 40.00                     | 30.00             |
| 1   | BOOT LID INNER LOCK                        | JAMMED        | 411.70                    | 295.00            |
| 1   | BOOT LID INNER LOCK ACTUATOR               | DAMAGED       | 193.50                    | 193.50            |
| 1   | BOOT LID LOCK CATCH                        | NOT NECESSARY | 46.20                     | -                 |
| 1   | BOOT LID WEATHERSTRIP                      | CUT           | 195.50                    | 195.50            |
| 2   | BOOT LID HINGES @\$88.20                   | BENT          | 176.40                    | 176.40            |
| 1   | REAR BUMPER                                | DISTORTED     | 691.10                    | 545.00            |
| 2   | REAR BUMPER SIDE RETAINERS @\$91.40        | NECESSARY     | 182.80                    | 112.00            |
| 2   | REAR BUMPER ATTACHMENT RETAINER @\$46.00   | NOT NECESSARY | 92.00                     | -                 |
| 1   | SET REAR BUMPER CLIPS                      | NECESSARY     | 50.00                     | 30.00             |
| 1   | REAR BUMPER REINFORCEMENT                  | BENT          | 365.60                    | 365.60            |
| 2   | REAR BUMPER REVERSE SENSOR @\$251.60       | DAMAGED       | 503.20                    | 503.20            |
| 2   | REAR BUMPER REVERSE SENSOR HOLDER @\$25.60 | NECESSARY     | 51.20                     | 51.20             |
| 2   | REAR BUMPER REFLECTORS @\$86.10            | N/S MISSING   | 172.20                    | 86.10             |
| 2   | TAILLAMPS @\$498.70                        | CRACKED       | 997.40                    | 750.00            |
| 2   | TAILLAMPS INNER SEALER @\$40.00            | NECESSARY     | 80.00                     | 40.00             |
| 2   | SET TAILLAMP CLIPS @\$25.00                | NECESSARY     | 50.00                     | 20.00             |
| 1   | TAILLAMP PANELS RH                         | BUCKLED       | 244.50                    | 244.50            |
| 1   | END PANEL                                  | DISTORTED     | 672.00                    | 672.00            |
| 1   | END PANEL TOP TRIM                         | DEFORMED      | 250.80                    | 250.80            |
| 1   | END PANEL TOP TRIM COVER                   | NOT NECESSARY | 48.00                     | -                 |
| 1   | SET END PANEL TOP TRIM CLIPS               | NOT NECESSARY | 30.00                     | -                 |

Report Ref No. CC4/FCI21009425/Ara3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts                          | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | REAR KEY ANTENNA SENSOR                       | NOT NECESSARY        | 218.90                    | -                 |
| 1   | SPARE TYRE PANEL                              | DISTORTED            | 1,077.50                  | 1,077.50          |
| 1   | SPARE TYRE PANEL TOP BOARD                    | TORN                 | 329.10                    | 245.00            |
| 1   | SPARE TYRE WHEEL NUT                          | NOT NECESSARY        | 56.10                     | -                 |
| 1   | REAR CHASSIS FRAME MEMBER RH                  | TO REPAIR SEE LABOUR | 1,455.10                  | -                 |
| 1   | REAR AIR VENT RH                              | NOT NECESSARY        | 69.20                     | -                 |
| 2   | REAR FENDER @\$1117.40                        | DISTORTED            | 2,234.80                  | 2,234.80          |
| 2   | REAR FENDERS INNER TRIMS @\$408.70            | TORN                 | 817.40                    | 610.00            |
| 2   | SET REAR FENDERS INNER TRIM CLIPS @\$30.00    | NECESSARY            | 60.00                     | 60.00             |
| 2   | REAR FENDER INNER SHIELD @\$1680.90           | NOT NECESSARY        | 3,361.80                  | -                 |
| 2   | SET REAR FENDER INNER SHIELD CLIPS @\$25.00   | NOT NECESSARY        | 50.00                     | -                 |
| 1   | REAR ROOF LINING                              | NOT NECESSARY        | 1,089.70                  | -                 |
| 1   | REAR WHEEL HOUSE PANEL LH                     | DISTORTED            | 798.60                    | 798.60            |
| 1   | REAR SPEAKER TOP BOARD                        | NOT NECESSARY        | 389.70                    | -                 |
| 2   | REAR SPEAKER TOP BOARD INNER TRIM @\$385.90   | NOT NECESSARY        | 771.80                    | -                 |
| 1   | REAR WINDSCREEN                               | SHATTERED            | 897.60                    | 897.60            |
| 1   | REAR WINDSCREEN MOLDING                       | NECESSARY            | 98.70                     | 98.70             |
| 1   | REAR WINDSCREEN INNER SEAL                    | NECESSARY            | 50.00                     | 50.00             |
| 1   | REAR EXHAUST SILENCER                         | NOT NECESSARY        | 794.50                    | -                 |
| 2   | REAR EXHAUST MOUNTINGS @\$55.20               | NOT NECESSARY        | 110.40                    | -                 |
| 1   | REAR EXHAUST GASKET                           | NOT NECESSARY        | 46.00                     | -                 |
| 1   | REAR EXHAUST SILENCER HEAT PLATE              | NOT NECESSARY        | 171.80                    | -                 |
|     | LESS 25% DISCOUNT                             |                      | -10,474.88                | -6,844.68         |
|     |                                               |                      | 31,424.62                 | 20,534.02         |
|     | <b><u>SPECIAL NETT ITEMS</u></b>              |                      |                           |                   |
| 1   | FRONT NO PLATE WITH COVER (SN)                | BENT                 | 50.00                     | 50.00             |
| 1   | REAR NO PLATE WITH COVER (SN)                 | BENT                 | 50.00                     | 50.00             |
| 1   | SET REVERSE SENSORS (SN)                      | DAMAGED              | 250.00                    | 200.00            |
| 1   | SET WINDSCREEN SEALANT (SN)                   | NECESSARY            | 80.00                     | 60.00             |
| 1   | SET END PANEL SEALANT (SN)                    | NECESSARY            | 80.00                     | 60.00             |
| 1   | SET SPARE TYRE PANEL FLOOR INSULATOR PAD (SN) | NECESSARY            | 120.00                    | 120.00            |

Report Ref No. CC4/FCI21009425/Ara3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

| Qty                                                                         | Description of Parts                                                    | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-------------------------------------------------------------------------|-----------|---------------------------|-------------------|
| 1                                                                           | RADIATOR COOLANT (SN)                                                   | NECESSARY | 40.00                     | 40.00             |
|                                                                             |                                                                         |           | 670.00                    | 580.00            |
|                                                                             | <b>LABOUR</b>                                                           |           |                           |                   |
|                                                                             | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR CHASSIS FRAME MEMBER RH . |           | 3,000.00                  | 2,900.00          |
|                                                                             | SPRAY PAINTING .                                                        |           | 3,000.00                  | 2,400.00          |
|                                                                             | CHECK WIRING ON HEADLAMP.                                               |           | 120.00                    | 30.00             |
|                                                                             | CHECK WIRING ON TAILAMP .                                               |           | 120.00                    | 30.00             |
|                                                                             | CHECK WIRING ON REVERSE SENSOR .                                        |           | 150.00                    | 50.00             |
|                                                                             | TO REMOVE AND INSTALL REAR WINDSCREEN .                                 |           | 120.00                    | 120.00            |
|                                                                             | TO REMOVE AND INSTALL INTERIOR UPHOSTERY .                              |           | 150.00                    | 150.00            |
|                                                                             | REMOVE AND INSTALL REAR FUEL TANK.                                      |           | 180.00                    | 80.00             |
|                                                                             | ANTI RUST.                                                              |           | 80.00                     | 80.00             |
|                                                                             | REMOVE AND INSTALL AIR CON.                                             |           | 150.00                    | 120.00            |
|                                                                             |                                                                         |           | 7,070.00                  | 5,960.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                         |           | <b>39,164.62</b>          | <b>27,074.02</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                         |           |                           | <b>16,800.00</b>  |

Report Ref No. CC4/FCI21009425/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKV 9547J

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SKV 9547J**

**RE-INSPECTION**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

