

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : YN2772Y

Accident Date 6/9/2021

Location SUNGEI KADUT AVE

Model: MITSUBISHI FE85D

(2/3/2012)

3P: 5025S (LONPAC)

TP Con Pac
Asher.

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front box o/s pillar <i>Dented</i>		1,500.00	1,500.00 <i>600</i>
2	4pcs	N/s box panel <i>Dented</i>	<i>2500</i>	10,000.00	10,000.00 <i>3000</i>
3	1 pc	N/s guide <i>New</i>		500.00	500.00 <i>X</i>
4	1 pc	Front o/s side mirror bracket <i>New</i>		300.00	300.00 <i>X</i>
5	1 pc	Front o/s side mirror <i>new</i>	865.40	165.40	165.40 <i>✓</i>
		Sub-Total:	865.40	12,465.40	0.00
		<i>SN: 3765-40</i>	25%	0%	0%
		After Less %:	649.05	12,465.40	0.00
		Labour			
1		To remove and replace damage parts		1,500.00	1,500.00 <i>400</i>
2		To spray painting.		400.00	400.00 <i>✓</i>
3		To check wiring.		120.00	120.00 <i>X</i>
4		To re-seal water proofing gum		100.00	100.00 <i>✓</i>
		Sub-Total:		1,920.00	
		Total:		15,034.45	
		After Less 20%:		12,027.56	

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)


Wheel: 4665-40

W/S: 3.7K

04 Days



8778 1999
24 hr accident call



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

YN2772Y ESTIMATEPg1

3.7K