

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SMR644T

Accident Date 6/9/2021

Location SUNGEI KADUT AVE

Model:

MAZDA 3

(19/1/2016)

3P: 5025S (LONPAC)

JM6BM42A860323420

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front o/s side mirror cover <i>Missing</i>	233.20	<i>135</i>	
2	1 pc	Front o/s side mirror <i>Missing</i>	636.40		
3	1 pc	Front o/s door <i>Repair</i>	1,259.20	<i>x</i>	
4	1 pc	Front o/s door weatherstrip	134.60	<i>x</i>	
5	1 pc	Front o/s door window seal (outer)	80.00	<i>x</i>	
6	2 pcs	Front o/s door hinges (upper & lower)	220.00	<i>x</i>	
7	1 pc	Front o/s door striker	146.50	<i>x</i>	
8	1 pc	Front o/s door lock	260.40	<i>x</i>	
9	1 pc	Front o/s door lock (catch)	110.00	<i>x</i>	<i>771.40</i>
10	1 pc	Front o/s door window channel	325.40	<i>x</i>	
11	1 pc	Front o/s door window channel bracket	87.50	<i>x</i>	<i>617.12</i>
12	1 pc	Front o/s door window motor	564.60	<i>x</i>	
13	1 pc	Rear o/s door	1,444.60	<i>x</i>	
14	1 pc	Rear o/s door weatherstrip	144.60	<i>x</i>	
Sub-Total:			5,647.00	0.00	0.00
			20%	0%	0%
After Less %:			4517.60	0.00	0.00
Labour					
1		To dismantle, straighten and welding	500.00	<i>200</i>	
2		To spray painting	600.00	<i>300</i>	
3		To remove and replace front and rear o/s door	150.00	<i>x</i>	
4		To remove and refit rear reverse sensor	60.00	<i>x</i>	
5		To remove and replace front o/s side mirror	100.00	<i>x</i>	
6		To check and reset fault code	180.00	<i>x</i>	
7		To check wiring	140.00	<i>x</i>	
8		To re-seal anti-rust	50.00	<i>x</i>	
Sub-Total:			1,780.00		
Total:			6,297.60		
After Less 20%:			5,038.08		

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

Adrian Lj
P/P 08/09/21
03 Days

total: 1117.12
(CP/P)



PAYNOW

