

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9096Z****AAD2109-014***Not Authorised**Resony Bk paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**07 SEP 2021****SHD 9096Z**

JTDKB3FU303078690

TOYOTA

PRIUS

4.9.2021

**AIG**

19/12/2018

**PART****LIST**

1	COVER, REAR BUMPER	\$	Bucina	442.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$		332.70	?
1	GUARD, REAR BUMPER, CENTER	\$	Wt / Dm	576.30	✓
1	SEAL, REAR BUMPER SIDE, LH	\$	Sn	88.50	X
1	RETAINER, REAR BUMPER SIDE, LH	\$	Sn	116.50	
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	Sn	650.30	
1	FILLER, REAR BUMPER EXTENSION, LH	\$	Sn	123.70	
1	FILLER, REAR BUMPER EXTENSION, RH	\$	Sn	123.70	
1	LENS AND BODY, REAR LAMP, LH (LOWER)	\$	Sn	502.00	
1	LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)	\$	Sn	443.30	
1	LENS AND BODY, REAR LAMP, RH (LOWER)	\$	Sn	502.00	
1	LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	\$	Sn	451.80	
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH	\$	Sn	54.40	
1	MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	\$	Sn	54.40	
1	PANEL SUB-ASSY, BACK DOOR	\$	R	1,147.80	
1	STAY ASSY, BACK DOOR, LH	\$	Sn	242.50	
1	STAY ASSY, BACK DOOR, RH	\$	Sn	242.50	
1	HINGE ASSY, BACK DOOR, LH	\$	R	61.00	
1	HINGE ASSY, BACK DOOR, RH	\$	R	61.00	
1	SPOILER SUB-ASSY, REAR	\$	Sn	1,575.40	
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$	R	925.60	
1	ORNAMENT SUB-ASSY, BACK DOOR	\$	Sn	47.90	✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$	Sn	54.60	✓
1	PLATE, BACK DOOR NAME, NO.1	\$	Sn	54.60	✓
1	COVER, REAR FLOOR (CTR)	\$	Sn	229.90	X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	Sn	241.90	X
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	Sn	175.10	X
<b>TOTAL</b>		<b>\$</b>		<b>9,522.00</b>	
<b>25%</b>		<b>\$</b>		<b>2,380.50</b>	
		<b>\$</b>		<b>7,141.50</b>	

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9096Z****AAD2109-014****Special Nett**

1SET REAR NUMBER PLATE WITH HOLDER

1 REAR BUMPER SIDE CLIP

1 BOOTLID STICKER 'TRANSCAB'

1 BOOTLID STICKER '65553333'

1SET PARKING AID

1SET REAR BUMPER CLIP

1 REAR BUMPER PROTECTOR

1 REAR BUMPER RETAINER CLIP

2SET TAILLAMP CLIP

TOTAL	\$	Sh	120.00	X
	\$	nn	60.00	50sn
Over All Total	\$	nn	100.00	30sn
	\$	nn	100.00	30sn
(PART-BY-PART) Repair Days	\$	Sh	700.00	X
	\$	nn	85.00	λ
	\$	nn	180.00	30sn
	\$	nn	75.00	X
	\$	nn	100.00	X
<b>TOTAL</b>	<b>\$</b>		<b>1,520.00</b>	

**TOTAL PARTS \$ 8,661.50****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas: \$ nn 240.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 2,000.00 200λ

To transfer of rear end panel fittings, attachment to facilitate bodywork repair. \$ nn 380.00 X

Putty And Spray Painting Of The Affected Portion. \$ 2,000.00 400λ

To reinstall rear bumper parking sensor. \$ 170.00 50λ

To transfer of tire, rim and on wheel balancing. \$ nn 170.00 X

To Check Electrical Lighting Concerned. \$ λ 170.00 X

To check steering geometry and computer wheel alignment \$ λ 220.00 X

To remove and refit of rear fender fittings, attachment and perform water seepage test. \$ λ 170.00 X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

**SHD 9096Z**

Towing Fee

\$ *nn* 200.00 X

**TOTAL** \$ **6,100.00**

**Over All Total** \$ **14,761.50**

**(PART-BY-PART) Repair Days**

~~8 Days~~

*2 days*

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

**Date:**