

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9096Z**AAD2109-014***Not Authored**Recovery B4 paint**2093.95*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 9096Z

JTDKB3FU303078690

TOYOTA

PRIUS

4.9.2021

AIG

19/12/2018

07 SEP 2021**PART****LIST**

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 LENS AND BODY, REAR LAMP, LH (**LOWER**)
- 1 LENS & BODY, REAR COMBINATION LAMP, LH (**UPPER**)
- 1 LENS AND BODY, REAR LAMP, RH (**LOWER**)
- 1 LENS & BODY, REAR COMBINATION LAMP, RH (**UPPER**)
- 1 MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR LH
- 1 MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 SPOILER SUB-ASSY, REAR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 ORNAMENT SUB-ASSY, BACK DOOR
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 COVER, REAR FLOOR (CTR)
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, FLOOR UNDER, NO.1 (LH)

\$	<i>Bucina</i>	442.60	✓
\$	<i>M</i>	332.70	✓
\$	<i>W1/M</i>	576.30	✓
\$	<i>S_L</i>	88.50	}
\$	<i>S_L</i>	116.50	
\$	<i>R</i>	650.30	
\$	<i>S_L</i>	123.70	
\$	<i>S_L</i>	123.70	
\$	<i>S_L</i>	502.00	
\$	<i>S_L</i>	443.30	
\$	<i>S_L</i>	502.00	
\$	<i>S_L</i>	451.80	
\$	<i>S_L</i>	54.40	
\$	<i>S_L</i>	54.40	}
\$	<i>R</i>	1,147.80	
\$	<i>S_L</i>	242.50	}
\$	<i>S_L</i>	242.50	
\$	<i>R</i>	61.00	}
\$	<i>R</i>	61.00	
\$	<i>S_L</i>	1,575.40	}
\$	<i>R</i>	925.60	
\$	<i>M</i>	47.90	✓
\$	<i>M</i>	54.60	✓
\$	<i>M</i>	54.60	✓
\$	<i>CM S_L</i>	229.90	✓
\$	<i>S_L</i>	241.90	X
\$	<i>S_L</i>	175.10	X

TOTAL \$ 9,522.00**25% \$ 2,380.50****\$ 7,141.50***123890*

Trans-cab Auto Services Pte Ltd**AAD2109-014**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9096Z**Special Nett**

1SET REAR NUMBER PLATE WITH HOLDER

\$ *Sn* 120.00 X

1 REAR BUMPER SIDE CLIP

\$ *nn* 60.00 *50sn*

1 BOOTLID STICKER 'TRANSCAB'

\$ *nn* 100.00 *30sn*

1 BOOTLID STICKER '65553333'

\$ *nn* 100.00 *30sn*

1SET PARKING AID

\$ *Sn* 700.00 X

1SET REAR BUMPER CLIP

\$ *nn* 85.00 X

1 REAR BUMPER PROTECTOR

\$ *nn* 180.00 *30sn*

1 REAR BUMPER RETAINER CLIP

\$ *nn* 75.00 X

2SET TAILLAMP CLIP

\$ *nn* 100.00 X**TOTAL \$ 1,520.00****TOTAL PARTS \$ 8,661.50****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,000.00 *200l*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ *nn* 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 2,000.00 *400l*

To reinstall rear bumper parking sensor.

\$ 170.00 *50l*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 X

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$ *nn* 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9096Z

Towing Fee

\$ *nn* 200.00 X

TOTAL \$ **6,100.00**

Over All Total \$ **14,761.50**

(PART-BY-PART) Repair Days

~~8 Days~~

2 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: