

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5180P**AAD2109-016***Not Authored*
Resumy Btqain

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 5180P

JTDKB3FU803078426

TOYOTA

PRIUS

4.9.2021

AIG

19/12/2018

07 SEP 2021

PART	LIST
1 COVER, REAR BUMPER	\$ 442.60 ✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ 332.70 ?
1 GUARD, REAR BUMPER, CENTER	\$ 576.30 ✓
1 FILLER, REAR BUMPER EXTENSION, RH	\$ 123.70 ✓
1 LENS AND BODY, REAR LAMP, RH (LOWER)	\$ 502.00 X
1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	\$ 451.80 X
1 MOULDING SUB-ASSY, ROOF DRIP SIDE FINISH, REAR RH	\$ 54.40 X
1 PANEL SUB-ASSY, BACK DOOR	\$ 1,147.80 X
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ 925.60
1 ORNAMENT SUB-ASSY, BACK DOOR	\$ 47.90 ✓
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$ 54.60 —
1 PLATE, BACK DOOR NAME, NO.1	\$ 54.60 —
1 COVER, FLOOR UNDER, NO.2 (RH)	\$ 241.90 X

TOTAL \$ 4,955.90**25% \$ 2,380.50****\$ 7,141.50****Special Nett**

1SET REAR NUMBER PLATE WITH HOLDER	\$ 120.00 X
1 REAR BUMPER SIDE CLIP	\$ 60.00 505AL
1 BOOTLID STICKER 'TRANSCAB'	\$ 100.00 305AL
1 BOOTLID STICKER '65553333'	\$ 100.00 305AL
1SET PARKING AID	\$ 700.00 X
1SET REAR BUMPER CLIP	\$ 85.00 X
1 REAR BUMPER PROTECTOR	\$ 180.00 X
1 REAR BUMPER RETAINER CLIP	\$ 75.00 X
2SET TAILLAMP CLIP	\$ 100.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5180P**AAD2109-016****TOTAL \$ 1,520.00****TOTAL PARTS \$ 8,661.50****LABOUR**To Rust-Proofing and apply undercoat Of The Affected Areas. \$ *nn* 240.00 *X*To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ *nn* 380.00 *X*Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 1,750.00 *2000*To transfer of rear end panel fittings, attachment to facilitate bodywork repair. \$ *nn* 380.00 *X*Putty And Spray Painting Of The Affected Portion. \$ 1,750.00 *4000*To reinstall rear bumper parking sensor. \$ 170.00 *500*To transfer of tire, rim and on wheel balancing. \$ *nn* 170.00 *X*To Check Electrical Lighting Concerned. \$ *nn* 170.00 *X*To check steering geometry and computer wheel alignment \$ *nn* 220.00 *X*To remove and refit of rear fender fittings, attachment and perform water seepage test. \$ *nn* 170.00 *X***TOTAL \$ 5,100.00****Over All Total \$ 13,761.50****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey (PART-BY-PART) Repair Days
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*7 DAYS**2 days*