

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19	9-96071	98-R	
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI21009436/Aqf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	14/01/2022	
			С	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMC 5984H	Veh. Inspected		GBJ 5236C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10011450/CD	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		08/09/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA DYNA	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTFAT35Y90K213133	Colour		RED	
	Odometer	77868 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	CONDOR		6 mm	
	L/H Front Tyre	195 R15C	CONDOR		6 mm	
	R/H Rear Tyre	155 R12C	CONDOR		6 mm	
	L/H Rear Tyre	155 R12C	CONDOR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	28/08/2021	Inspection Date		25/10/2021	
	Survey held at	YAP LEE MOTOR				
		BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883	-			
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	D)IN ACCORDANC	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: