

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJP82K Mercedes Benz GLC250

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 1,493.80 <i>de ✓</i>
2	2	Rear bumper bracket	\$ <i>RHX</i> 222.30 <i>LH-ver 111.15</i>
3	2	Rear bumper reflector	\$ <i>RHX</i> 186.40 <i>LH-ver 93.20</i>
4	1	Rear bumper tow cover	\$ 98.10 <i>de ✓</i>
5	2	Rear bumper retainer	\$ 387.90 <i>LH-de ✓ RHX 193.45</i>
6	1	Rear bumper reinforcement	\$ ✓ 809.60 <i>bt 764.50</i>
7	1	Rear bumper centre chrome moulding	\$ 295.10 <i>cu ✓</i>
8	1	Rear bumper inner beam <i>plastic bracket</i>	\$ 495.50 <i>de 278 ✓</i>
9	1	Rear tailgate assy	2525 \$ 3,549.60 <i>bb</i>
10	1	Rear tailgate weatherstrip	\$ 188.10 <i>an ✓</i>
11	1	Rear tailgate inner board	\$ 526.40 <i>cu ✓</i>
12	1	Rear tailgate centre logo	\$ 174.90 <i>ne 101</i>
13	1	Rear tailgate 'GLC 250' emblem	\$ 133.40 <i>re 98</i>
14	1	Rear tailgate '4matic' emblem	\$ 133.40 <i>re 98</i>
15	1	Rear tailgate lock mechanism	\$ 380.50 <i>bb 318</i>
16	1	Rear tailgate lock catch	\$ 85.60 <i>X</i>
17	2	Rear tailgate number plate lamp	\$ 188.10 <i>X</i>
18	1	Rear tailgate auto switch	\$ 281.50 <i>X</i>
19	2	Rear tailgate inner handle	\$ 363.80 <i>X</i>
20	1	Rear tailgate inner lamp	\$ 88.80 <i>X</i>
21	2	Rear tailgate dampers	\$ 592.90 <i>X</i>
22	2	Rear tailgate hinges	\$ 266.70 <i>X</i>
23	2	Rear tailgate rubber stopper	\$ 82.90 <i>re</i>
24	1	Rear left tailgate taillamp	585 \$ 762.40 <i>an</i>
25	1	Rear right tailgate taillamp	585 \$ 762.40 <i>an</i>
26	1	Rear left taillamp	645 \$ 812.20 <i>an</i>
27	1	Rear right taillamp	645 \$ 812.20 <i>an</i>
28	1	Rear left taillamp bracket	\$ 261.20 <i>de 180</i>
29	1	Rear right taillamp bracket	\$ 261.20 <i>de 180</i>
30	1	Rear end lower panel	\$ 1,545.10 <i>bb 1399</i>
31	1	Rear end lower panel top garnish	\$ 172.50 <i>de</i>
32	1	Rear exhaust muffler complete assy	\$ 3,678.90 <i>bt 21980</i>
33	2	Rear exhaust muffler rubber mounting	\$ 88.90 <i>de</i>
34	1	Rear left exhaust end cover	295 \$ 450.10 <i>bt ✓</i>
35	1	Rear right exhaust end cover	\$ 450.10 <i>X nn</i>
36	2	Rear exhaust heat shield	496 \$ 603.40 <i>bt</i>
37	1	Rear windscreen glass moulding	\$ 288.80 <i>re</i>
38	1	Rear windscreen glass centre garnish	\$ 168.90 <i>re</i>
39	2	Rear windscreen glass side inner garnish	\$ 265.30 <i>re</i>
40	1	Rear floor panel	\$ 1,825.20 <i>XRX</i>
41	1	Rear floor panel carpet	\$ 382.50 <i>X nn</i>
42	1	Rear top board	\$ 398.50 <i>X nn</i>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJP82K Mercedes Benz GLC250

No	Qty	Parts Description	Estimated Parts Price
43	1	Rear left fender	\$ 2,807.80 x nn
44	1	Rear right fender	\$ 2,807.80 x nn
45	1	Rear left fender side protector	\$ 298.20 de
46	1	Rear right fender side protector	\$ 298.20 x
47	1	Rear left quarter glass moulding	\$ 280.30 x
48	1	Rear right quarter glass moulding	\$ 280.30 x
49	1	Rear left air duct ventilator	\$ 80.30 x
50	1	Rear right air duct ventilator	\$ 80.30 x
51	1	Front left passenger headrest restraint	\$ 985.10 x
52	1	Front right driver headrest restraint	\$ 985.10 x
less 10%			\$ 33,918.50
			\$ 3,391.85
			\$ 30,526.65

Special Nett Items

1	10	Rear bumper clips	\$ 60.00 nei
2	6	Rear end lower panel top garnish clips	\$ 40.00 2one
3	1	Rear end lower panel sealant	\$ 120.00 5one
4	4	Rear bumper reverse sensor	\$ 1,600.00 nn / 600
5	4	Rear bumper centre chrome moulding clips	\$ 40.00 2one
6	1	Rear no plate with garnish	\$ 100.00 x nn
7	1	Rear bumper lower spoiler	\$ 1,600.00 de
8	1	Rear bumper lower spoiler sealant	\$ 100.00 2one x nn
9	12	Rear bumper lower spoiler clips	\$ 80.00 2one
10	1	Rear floor panel insulator pad	\$ 180.00 x
11	1	Rear floor panel sealant	\$ 180.00 x
12	1	Rear view camera	\$ 450.00 x
13	8	Rear tailgate inner board clips	\$ 50.00 2one
14	1	Rear windscreen glass sealant	\$ 100.00 6one
15	1	Rear left fender sealant	\$ 100.00 x
16	1	Rear right fender sealant	\$ 100.00 x
17	8	Rear windscreen glass centre garnish clips	\$ 50.00 x
18	2 set	Rear windscreen glass side inner garnish clips	\$ 80.00 x
19	1	Rear left quarter glass sealant	\$ 80.00 x
20	1	Rear right quarter glass sealant	\$ 80.00 x
21	6	Rear left fender side protector clips	\$ 80.00 x
22	6	Rear right fender side protector clips	\$ 40.00 1one
			\$ 40.00 x nn
			\$ 5,270.00

Total parts

\$ 35,796.65

1540

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJP82K Mercedes Benz GLC250

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,600.00 <i>900 950</i>
2	To putty and spray painting rear portion.	\$ 1,600.00 <i>900 950</i>
3	To check rear lighting and wiring.	\$ 50.00 <i>30</i>
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 <i>60</i>
5	To remove and install rear exhaust muffler assy.	\$ 120.00 <i>80</i>
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 <i>60</i>
7	To apply anti rust proofing to rear affected area.	\$ 140.00 <i>40</i>
8	To remove and install rear bumper reverse sensor.	\$ 80.00 <i>30</i>
9	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 <i>120</i>
10	To remove and install rear view camera.	\$ 80.00 <i>X un</i>
11	To remove and install rear fuel tank to facilitate the repair.	\$ 250.00 <i>X un</i>
12	To use diagnostic equipment to scan and calibrate rear electrical system.	\$ 350.00 <i>200</i>
13	To use diagnostic equipment to scan for fault code, erased and reset if necessary.	\$ 350.00
14	To remove and install rear left quarter glass.	\$ 80.00 <i>X un</i>
15	To remove and install rear right quarter glass.	\$ 80.00 <i>X un</i>
16	Towing service.	\$ 120.00 <i>X un</i>
17	To remove and install front left passenger headrest restraint system.	\$ 300.00 <i>X</i>
18	To remove and install front right driver headrest restraint system.	\$ 300.00 <i>X</i>
19	To reset front air bag lamp.	\$ 300.00 <i>X</i>
Total labour :		\$ 6,160.00

2520

Tanpin 92495749
up 8/9/21 e 4pm
To check part prices
4/5 reply after my
Tanpin 92495749

7 days
13979.61
1540
2520
18039.61
45814400
2 days

Total parts : \$ 35,796.65
Total labour : \$ 6,160.00
Total repair cost : \$ 41,956.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

