

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009441/UES3Q2
Date: 15/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210014319
Claimant Vehicle No :	SLQ6593J	Insured Vehicle No :	SLA7406U
Date of Loss:	07/09/2021	Nature of Claim:	TP
		Claim No:	0143311503SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ6593J	Engine No:	4A92CL9273
Make & Model:	MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A)	Chassis No:	JMYSRCY1AGU006213
Reg. Date:	19/07/2017 (Man. Year: 2016)	Odometer:	88038 km
Colour:	White		
Engine Capacity:	1590 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,288.00	1,919.70	4,368.30	69.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,590.00	1,350.00	45.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,228.00	3,509.70	5,718.30	61.97
Approved Total (Overridden) (S\$)		2,800.00		

(S\$)	9,228.00	2,800.00	6,428.00	69.66
+ GST 7.00/7.00% (S\$)	645.96	196.00	449.96	69.66
Nett Amount (S\$)	9,873.96	2,996.00	6,877.96	69.66
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,198.00		

INSPECTION

Date of Assignment: 08/09/2021

Date Inspected: 08/09/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP O/S	Scratched	900.00 F	*450.00 FL
2	1		*REAR BUMPER	Distorted	1,081.00 F	*861.00 FL
3	1		*REAR BUMPER SIDE RETAINER O/S	Bent	85.00 F	*25.00 FL
4	1		*REAR BUMPER REFLECTOR O/S	Not Necessary	62.00 F	*- FL
5	1		*REAR BUMPER BEAM	Not Necessary	292.00 F	*- FL
6	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
7	1		*REAR END PANEL	Repair	514.00 F	*- FL
8	1		*REAR FENDER O/S	Repair	987.00 F	*- FL
9	1		*REAR FENDER UNDER SHIELD O/S	Deformed	66.00 F	*66.00 FL
10	1		*SET REAR FENDER UNDER SHIELD CLIPS O/S	Necessary	30.00 F	*30.00 FL
11	1		*REAR FENDER LOWER PANEL O/S	Dented	651.00 F	*651.00 FL
12	1		*REAR SPORT RIM O/S	Repair	900.00 F	*- FL
13	1		*REAR SHOCK ABSORBER O/S	Not Necessary	350.00 F	*- FL
14	1		*REAR WHEEL BEARING O/S	Not Necessary	320.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,288.00	2,133.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	213.30
Total Parts (\$)	6,288.00	1,919.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	100.00
4	TO DISMANTLE & REFIX REAR UNDER CARRIAGE	New	180.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
6	TO SPRAY RUST PROOFING	New	80.00	30.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	980.00	650.00
8	TO PUTTY & SPRAY PAINTING	New	1,300.00	680.00
Gross Labour Cost (S\$)			2,940.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >