

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep Stc.

have rides at Rolden have 6/11

22/9/14 1/3 @ 2800 confirmed with Alan

Veh No:

SLQ 65937

Yr Regn:

17/7/17

Type: M.Cdr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA1

Make:

mit Lancer

C.C

1590

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

AP038

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSRCYIAG400 6213

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

7/9/14

D.O.I.

8/9/14

Survey held at

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

o/s Rear

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Ukh Asher

Not Appointed

8/9/21

2/5 \$ 2800
4 days

VEHICLE No: SLQ 6593J

Not item

1PC	TAILLAMP O/S	Scr	450.00	\$900.00
1PC	REAR BUMPER	Dis	861.00	\$1,081.00
1PC	REAR BUMPER SIDE RETAINER O/S	Scr	25.00	\$85.00
1PC	REAR BUMPER REFLECTOR O/S	11		\$62.00 X
1PC	REAR BUMPER BEAM	11		\$292.00 X
1SET	REAR BUMPER CLIPS	11		\$50.00
1PC	REAR END PANEL	12		\$514.00 X
1PC	REAR FENDER O/S	R		\$987.00 X
1PC	REAR FENDER UNDER SHIELD O/S	De		\$66.00
1SET	REAR FENDER UNDER SHIELD CLIPS O/S	11		\$30.00
1PC	REAR FENDER LOWER PANEL O/S	20		\$651.00
1PC	REAR SPORT RIM O/S	R		\$900.00 X
1PC	REAR SHOCK ABSORBER O/S	11		\$350.00 X
1PC	REAR WHEEL BEARING O/S	11		\$320.00 X
				\$6,288.00

10%

TO CHECK WIRING
TO DISMANTLE & REFIX REAR REVERSE SENSOR
TO DISMANTLE & REFIX CUSHION UPHOLSTERY
TO DISMANTLE & REFIX REAR UNDER CARRIAGE
TO CONDUCT WHEEL ALIGNMENT
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20
\$80.00 50
\$120.00 100
11 \$180.00 X
\$150.00 60
\$80.00 30
\$980.00 650
\$1,300.00 680
TOTAL \$9,228.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P.2133

10%

9799.70

1-1590

3508.7
202
2807