

ASS. REC. BY: *Marcus*

REF:

CC6/CT/21009445/4653

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

13.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

B

Vehicle: IN / OUT

Date:

Person Contacted:

19360

Date / Time

Action / Instruction

*Dep 8:00**have v. des at After have 6.1A*

Veh No:

GP 9860H

Yr Regn:

30/5/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

*Nissan**NV350*

c.c

2488

Colour:

brown

A/C:

Insured / Std / NI / NA

Sp. Reading

163349

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1MC2E2620004278

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: *NV* / S/Rim / STD A/Rim or

Tyre Size:

F:

195-R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

6/9/12

D.O.I.

8/9/14

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) *S + RS* *SI*☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

21/9/14 9/12 912.32 confirmed with Alan.

Luu Joseph

Not Acknowled
8/9/21
P/P 912-32
2 days.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: GP 9860H

NETT ITEM

1PC TAILLAMP O/S
1PC REAR BUMPER
1SET REAR BUMPER CLIPS

scr \$224.80 ✓
R \$667.20 X
11 \$39.00 X
\$931.00

(10%)

TO CHECK WIRING
TO DISMANTLE & REFIX REAR REVERSE SENSOR
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20
\$60.00 40
\$480.00 250
\$600.00 400
TOTAL \$2,121.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-224.80
10%
P-202.32
L-710.00
912-32