

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0723/2021/KS
DATE : 2-Sep-21
WIP : 42634

Hui Zhen

\$13758.88

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHIEW YEW SENG RICHARD
ADDRESS : 68 TOH TUCK ROAD
#02-08
SINGAPORE 596733
TELEPHONE : HP +65 97925796
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070149534
VEHICLE NO : **SMV 9101 M**
MODEL CODE : AUDI A5 CABRIOLET 2.0 TFSI
MODEL YEAR : 27/10/2021
ENGINE NO : DEM 025618
CHASSIS NO : WAUZZZF50MA003532
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Sep-21
PLACE OF ACCIDENT : CLEMENTI AVE 6

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICL. SMV 9101 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00 1000	✓
4	✓ ✓ TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00 1100	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,122.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9101 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Dented</i>	1	\$ 2,342.00 ✓	1873.60	
2	FRONT BUMPER SECURING STRIP <i>new</i>	1	\$ 72.00 +		
3	FRONT BUMPER LOWER GRILLE - CENTER <i>new</i>	1	\$ 196.00 +		
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 262.00 +		
5	FRONT BUMPER AIR GUIDE - RH <i>new</i>	1	\$ 63.00 +		
6	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 262.00 +		
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 135.00 +		
8	FRONT BUMPER TRIM - RH <i>new</i>	1	\$ 48.00 +		
9	FRONT BUMPER TRIM - CENTER <i>new</i>	1	\$ 114.00 +		
10	RADIATOR GRILLE <i>new</i>	1	\$ 1,694.00 +		
11	FOAM FILLER PIECE <i>new</i>	1	\$ 146.00 +		
12	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 845.00 +		
13	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 127.00 +		
14	"CAUTION" STICKER <i>new</i>	1	\$ 14.00 +		
15	"A/C" STICKER <i>new</i>	1	\$ 8.00 +		
16	LOCK CARRIER BRACKET <i>new</i>	1	\$ 137.00 +		
17	LOCK CARRIER BRACKET SUPPORT- LH / RH <i>new</i>	2	\$ 58.00 +		
18	BONNET <i>Dented</i>	1	\$ 3,312.00 ✓	2649.60	
19	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 123.00 +		
20	BONNET IMPACT PROTECTION - CENTER <i>new</i>	1	\$ 28.00 ✓	21.84	
SUB TOTAL SPARE PARTS		:	\$ 9,986.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9101 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET IMPACT PROTECTION - LH / RH <i>new</i>	2	\$ 58.00 ✓	43.84
22	BONNET STRIKER - RH <i>new</i>	1	\$ 214.00 +	
23	LED HEADLIGHT - RH <i>cond</i>	1	\$ 7,685.00 ✓	6148
24	HEADLIGHT BREATHER HOSE - RH <i>new</i>	1	\$ 36.00 +	
25	LIFT CYLINDER - RH <i>? new</i>	1	\$ 198.00 +	
26	LIFT CYLINDER HOSE	1	TBC +	
27	RADIATOR AIR GUIDE - RH	1	\$ 32.00 +	
28	RADIATOR AIR GUIDE - RH	1	\$ 16.00 +	
29	RADIATOR AIR GUIDE - UPPER	1	\$ 16.00 +	
30	FRONT NO PLATE	S/N	\$ 60.00 +	
31	SUNDRIES <i>Nol nec.</i>		\$ 300.00 X	
TOTAL SPARE PARTS		:	\$ 18,601.00	
TOTAL LABOUR CHARGES		:	\$ 5,122.00	
GRAND TOTAL		:	\$ 23,723.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adam Lj
SURVEYED DATE : 07/09/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 04 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT