



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

Steve (CLKK)
8/9/21, 12 pm

will PL
13 days
PIP
My BLSy

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Tan Choo Pee 3 Yishun Street 51 #08-05 Singapore 767997 Mobile: 97805802	
		Document No. 0		
		Document Date 07/09/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2014	ZRE171R	GEXGKZ S1	27/08/2014	SKP2530J	0	64610	SKP2530J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053REH104510561	1ZRX423279	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:CHINA TAIPING INSURANCE TP VEH:SJL731S DATE OF ACC:05.09.2021				50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) - FRONT				100 300.00
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP - FRONT				122.40
4	S	BP-SUBLET R/I AC CONDENSOR, PIPING AND REGAS - FRON T				350.00
5	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				130.00
6	L	BP-LPO SUPPLY REGN PLATE (PO#) -FRT & BA CK				80 160.00
7	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS - FRONT				1800 3600.00
8	B	BP-RES2 RESPRAY ACC AFFECTED AREAS - FRONT				1770 3540.00
9	Z	BP-SLANT SUPPLY SEALANT (NETT) - REAR				200 300.00
10	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR - REAR				180.00
11	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST - RE AR				122.40

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-850000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICC11	Mr Tan Choo Pee 3 Yishun Street 51 #08-05 Singapore 767997 Mobile: 97805802	
		Document No. 0		
		Document Date 07/09/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2014	ZRE171R	GEXGKZ S1	27/08/2014	SKP2530J	0	64610	SKP2530J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053REH104510561	1ZRX423279	60	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	B	BP-LAB2 REMOVE AND TRANSFER BOOTLID COMPONENTS ONTO NEW BOOTLID.				540.00
13	B	R/I REAR REVERSE CAMERA TO FAC REPAIR. - REAR				720.00
14	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR - REAR				3600.00
15	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS- REAR	4 x 720			3540.00
16	B	BP-RES2 RESPRAY ACC AFFECTED AREAS- REAR	1.00	155.20		155.20
17	1	SPZ061-12028 17 1D4 SILVER METALLIC REVERSE SE	1.00	536.20		536.20
18	2	S52119-0Z955 COVER,FR BUMPER	10.00	4.10		41.00
19	3	S52161-0K040 PIECE,RR BUMPER	1.00	86.10		86.10
20	4	S52115-02270 SUPPORT,FR BUMPER RH	1.00	86.10		86.10
21	5	S52116-02270 SUPPORT,FR BUMPER LH	1.00	171.70		171.70
22	6	S53112-02630 GRILLE,RADIATOR LWR	1.00	90.80		90.80
23	7	S52611-02310 ABSORBER,FR BUMPER	1.00	403.70		403.70
24	8	S52131-02190 REINFORCEMENT,FR	2.00	2.60		5.20
25	9	T90467-05170 CLIP	2.00	8.70		17.40
26	0	T53879-58010 RETAINER, FR FENDER	1.00	648.30		648.30
27	1	S53100-02760 GRILLE,RADIATOR				

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Company Copy

ESTIMATE

Account Details				Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept				S1000003 / ICCI1		Mr Tan Choo Pee 3 Yishun Street 51 #08-05 Singapore 767997 Mobile: 97805802			
				Document No. 0					
				Document Date 07/09/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2014	ZRE171R	GEXGKZ S1	27/08/2014	SKP2530J	0	64610	SKP2530J		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MR053REH104510561		1ZRX423279	60	Thomas Pang W T	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
27	2	S53141-02110	COVER,RADIATOR RH	?	X n n	1.00	81.30		81.30
28	3	S53301-02310	HOOD SUB-ASSY	?	00	1.00	1259.40		1259.40
29	4	S53381-02210	SEAL,HOOD	?	X n n	1.00	32.30		32.30
30	5	S90467-09050	CLIP	?	n n	6.00	2.90		17.40
31	6	S53510-02671	LOCK ASSY,HOOD	X	n n	1.00	136.20		136.20
32	7	S53410-02360	HINGE ASSY,HOOD RH	X	n n	1.00	59.40		59.40
33	8	S53420-02360	HINGE ASSY, HOOD,LH	X	n n	1.00	59.40		59.40
34	9	S53208-02210	SUPPORT SUB-ASSY, HO	?	X n n	1.00	151.10		151.10
35	0	T53201-02370	SUPPORT SUB-ASSY,	?	X n n	1.00	1149.50		1149.50
36	1	S75311-02190	RADIATOR GRILLE EMBLEM,	?	n n	1.00	48.40		48.40
37	2	S75444-02700	PLATE, LUGGAGE COMPT	?	X n n	1.00	35.90		35.90
38	3	S75444-02A20	PLATE, LUGGAGE COMPT	?	X n n	1.00	35.90		35.90
39	4	S88450-02350	A/C CONDENSER ASSY,	?	X n n	1.00	1820.20		1820.20
40	5	S16410-0D390	RADIATOR ASSY	?	X n n	1.00	2169.60		2169.60
41	6	S81110-02F51	HEADLAMP ASSY,RH	?	00	1.00	3028.80		3028.80
42	7	S81150-02F51	HEADLAMP ASSY,LH	?	X n n	1.00	3028.80		3028.80
43	8	S52159-0Z904	COVER,RR BUMPER	?	00	1.00	561.50		561.50
44	9	S52161-0K040	PIECE,RR BUMPER	?	n n	10.00	4.10		41.00
45	0	S52575-02140	RETAINER,RR BUMPER R	?	X n n	1.00	110.50		110.50
46	1	S52562-02250	RETAINER,RR BUMPER R	?	X n n	1.00	61.00		61.00
For & on behalf of			Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd									
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
							Amount Due		

Company Copy



Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no. : 6631-1188

ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		Mr Tan Choo Pee 3 Yishun Street 51 #08-05 Singapore 767997 Mobile: 97805802		
			Document No.				
			0				
			Document Date				
			07/09/2021				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2014	ZRE171R	GEXGKZ S1	27/08/2014	SKP2530J	0	64610	SKP2530J

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR053REH104510561	1ZR423279	60	Thomas Pang W T	--/--	0.00 --/--

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
47	2	S52576-02140 RETAINER,RR BUMPER L ? X nn	1.00	110.50		110.50
48	3	S52563-02250 RETAINER,RR BUMPER L X nn	1.00	61.00		61.00
49	4	S52023-02190 REINFORCEMENT,RR -- 00	1.00	403.70		403.70
50	5	S52181-02190 ARM,RR BUMPER RH ? X nn	1.00	68.70		68.70
51	6	S52182-02160 ARM,RR BUMPER LH ? X nn	1.00	68.70		68.70
52	7	S58307-02380 PANEL,LAMP LOWER -- 00	1.00	676.60		676.60
53	8	S64401-02B71 PANEL SUB-ASSY, LUGG -- 00	1.00	798.90		798.90
54	9	S64461-02220 WEATHERSTRIP,LUGGAGE -- TN	1.00	177.60		177.60
55	0	S64503-02180 ARM,LUGGAGE ? X nn	1.00	70.50		70.50
56	1	S64503-02180 ARM,LUGGAGE ? X nn	1.00	70.50		70.50
57	2	S64600-02080 LOCK ASSY,LUGGAGE ? X nn	1.00	403.70		403.70
58	3	S58387-02240 PLATE,RR FLOOR X nn	1.00	244.30		244.30
59	4	T90467-08186 CO CLIP -- nk	2.00	2.90		5.80
60	5	S64771-02390 CO COVER ASSY,SPARE ? X nn	1.00	269.30		269.30
61	6	S81550-02780 LAMP ASSY,RR COMB RH -- CUT	1.00	383.60		383.60
62	7	S81560-02780 LAMP ASSY, RR COMBIN (LH) -- CUT	1.00	383.60		383.60
63	8	S81580-02550 R/REAR BOOT LAMP X nn	1.00	356.60		356.60
64	9	S81590-02550 LAMP ASSY,RR LH X nn	1.00	356.60		356.60
65	0	S81910-02170 REFLECTOR ASSY, REFL X nn	1.00	60.40		60.40
66	1	S81920-02110 REFLECTOR ASSY, REFL X nn	1.00	60.40		60.40

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Company Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462. Tel no. 6631 1189

ESTIMATE

Account Details			Account No.		Customer Details			
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		Mr Tan Choo Pee 3 Yishun Street 51 #08-05 Singapore 767997 Mobile: 97805802			
			Document No. 0					
			Document Date 07/09/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2014	ZRE171R	GEXGKZ S1	27/08/2014	SKP2530J	0	64610	SKP2530J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053REH104510561		1ZR423279	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
67	2	T89997-30070 ELECTRICAL ANTENNA, <i>X 1/1</i>			1.00	194.20		194.20
68	3	S75431-02090 LUGGAGE COMP EMBLEM, <i>1/1</i>			1.00	62.20		62.20
69	4	S75442-02330 PLATE, LUGGAGE COMPT <i>1/1</i>			1.00	41.40		41.40
70	5	S75442-02340 PLATE, LUGGAGE COMPT <i>1/1</i>			1.00	46.00		46.00
LKW Auto Consultants hence notify the Repairer of the following: - To remedy before after spray painting - To display damaged parts during remedy - Parts prices are subject to confirmation - This policy is on a "With out prejudice" basis - No legal liability of LKW is derived - Signature of the Rep (S) of the customer and Insurer, Insurer, Borneo Motors Company								
For & on behalf of		Customer's Signature		Charge Summary		Total		38,868.90
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts 21,504.10 Labour 16,664.80 Sublet 700.00 Lubrication/Fluid 0.00 Others 0.00		GST 7.00% 2,720.82 Less 0.00 Amount Due 41,589.72		

Company Copy