

Our Ref: SLK9943U
 Your Ref: SLS9774Z

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	FRONT GRILLE ?cm/		\$ 385.90 ✓
2	1	FRONT GRILLE LOGO ?nr/		\$ 75.30 ✓
3	1	HEADLAMP RH cm/		\$ 1,866.50 ✓
4	1	HEADLAMP LH Xnr		\$ 1,866.50 X
5	1	FRONT BUMPER repair		\$ 738.10 XR
6	1	FRONT BUMPER SPONGE ?Xnr		\$ 155.30 X
7	1	FRONT BUMPER REINFORCEMENT Xnr		\$ 332.90 X
8	1	FRONT SUPPORT PANEL UPPER Xnr		REPAIR X
9	1	HEADLAMP PANEL RH Xnr		REPAIR X
10	1	FRONT SUPPORT BRACE PANEL Xnr		\$ 115.30 X
11	1	AIR CON CONDENSER Xnr		\$ 1,235.90 X
12	1	REAR FENDER RH Xnr		REPAIR X
13	1	REAR FENDER LH Xnr		REPAIR X
14	1	REAR BOOT LID bt/		\$ 1,165.30 756
15	1	REAR BOOT LID LOGO nr/		\$ 75.30 ✓
16	1	REAR BOOT LID CHROME ?cm/		\$ 388.90 280
17	1	REAR BOOT LID REVERSE LAMP RH Xnr		\$ 625.30 X
18	1	REAR BOOT LID REVERSE LAMP LH cm/		\$ 625.30 342
19	1	REAR BOOT LID HINGE RH Xnr		\$ 189.50 X
20	1	REAR BOOT LID HINGE LH Xnr		\$ 189.50 X
21	1	REAR BOOT LID LOCK Xnr		\$ 285.10 X
22	1	REAR TAIL LAMP RH Xnr		\$ 838.50 X
23	1	REAR TAIL LAMP LH \$su/		\$ 838.50 480
24	1	REAR TAIL LAMP PANEL RH Xnr		\$ 269.10 X
25	1	REAR TAIL LAMP PANEL LH Xnr		\$ 269.10 X
26	1	REAR BUMPER de/		\$ 685.90 545
27	1	REAR BUMPER SIDE RETAINER RH Xnr		\$ 53.10 X
28	1	REAR BUMPER SIDE RETAINER LH Xnr		\$ 53.10 X
29	1	REAR BUMPER REINFORCEMENT bt/		\$ 421.30 395
30	1	REAR BOOT LID WEATHERSTRIP nr/		\$ 195.60 ✓
31	1	REAR END PANEL bt/		\$ 1,032.50 695
32	1	REAR END PANEL GARNISH de/		\$ 266.90 ✓
33	1	REAR FENDER INNER TRIM LH Xnr		\$ 585.10 X
			SUB TOTAL	\$ 15,824.60
			LESS 25%	\$ 3,956.15
			TOTAL AMOUNT	\$ 11,868.45

6358.50
 25%
4768.81

Our Ref: **SLK9943U**
 Your Ref: **SLS9774Z**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT BUMPER CLIPS 20 XAN		\$ 50.00 XAN
2	1	FRONT NUMBER PLATE & HOLDER 30		\$ 60.00 750
3	1	AIR CON GAS XAN		\$ 100.00 XAN
4	1	REAR NUMBER PLATE & HOLDER 50		\$ 60.00 350
5	1	REAR REVERSE CAMERA 1 XAN		\$ 350.00 250? X
6	1	REAR BUMPER CLIPS 1		\$ 50.00 30
7	1 SET	REAR BUMPER REVERSE SENSORS 1 XAN		\$ 250.00 200? X
8	1	REAR TAIL LAMP PANEL SEALANT RH & LH XAN		\$ 100.00 XAN
9	1	REAR END PANEL SEALANT 1		\$ 80.00 40
			SUB TOTAL	\$ 1,100.00
			TOTAL PARTS COST	\$ 12,968.45

Our Ref: **SKX1582Z**
 Your Ref: **SLS9774Z**

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 1,200.00 700
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 100.00 XAN
3	TO CONDUCT DIGNOSIS FAULT CODE & RESET	\$ 150.00 80
4	TO REMOVE & REFIT AIR CON CONDENSER & RADIATOR	\$ 120.00 XAN
5	TO REMOVE & REFIT REAR BUMPER REVERSE SENSORS & CAMERA	\$ 100.00 60
6	TO REMOVE & REFIT UPHOSTERY, GARNISH AND ATTACHMENT PARTS	\$ 120.00 60
7	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 1,500.00 800
8	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 60.00 40
9	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 60.00 20
10	TO VACUUM, WAXING & CLEAN	\$ 60.00 XAN
11	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 50.00 30
TOTAL BEFORE GST		\$ 16,488.45
GST 7%		\$ 1,154.19
TOTAL (PARTS & LABOUR):		\$ 17,642.64

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$ 17,600.00** for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng
 Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental work must be disclosed and is subject to approval

Acknowledged by:
 Signature:
 Date:

4768.87
 170.00
 1790.00
 6728.87
 20%
 5383.10

L/S - \$5,400

RASUL
 Hp 90010068
 7 days
 L/S
 08/09/21 @ P230
 Resurvey after repair